

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
2040 South Pacheco  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30005-60794
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/> <u>Injection Well</u>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Concho Oil & Gas Corp.		6. State Oil & Gas Lease No.
3. Address of Operator 110 W. Louisiana Ste 410; Midland, Tx 79701		7. Lease Name or Unit Agreement Name:  Twin Lakes San Andres Unit
4. Well Location  Unit Letter <u>P</u> : <u>990</u> feet from the <u>South</u> line and <u>990</u> from the <u>East</u> line  Section <u>01</u> Township <u>9S</u> Range <u>28E</u> NMPM Chaves County		7. Well No.  86
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3962 GR		8. Pool name or Wildcat Twin Lakes; San Andres (Assoc)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐  
OTHER: Clean out & Stimulate ☒

SUBSEQUENT REPORT OF:

- REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Concho Oil & Gas Corp. respectfully requests approval to clean out to PBTD & stimulate the Twin Lakes San Andres Unit No. 86 according to the following procedure:

1. TIH w/ packer and test casing to 300#. If ok, proceed.
2. TIH w/ bit, scraper, DC's and work string.
3. Clean out to PBTD @ 2725'.
4. POOH laying down workstring.
5. Test injection string in hole.
6. Contact OCD and run MIT test.
7. Acidize w/ 500 gals xylene and 1500 gals 20% NE w/ xylene w/ produced water.
8. Flow back all load water. (do not swab)
9. Return to injection. → Run MIT AS Per Rule 19.15.9. 704. A

Notify OCD 24 hrs. prior to any work done



Wellbore diagram attached.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Production Analyst DATE 9-25-01

Type or print name Terry Stathem Telephone No. 915/683-7443  
(This space for State use)

APPROVED BY [Signature] TITLE Wild Dog DATE 10-1-01  
Conditions of approval, if any:


# TLSAU #86

Formerly - O'Brien E #4

Lease No.: 24988      Dist. No. :      County: Chaves      Field: Twin Lakes San Andres  
 Section: 1      Twsp: 9S      Range: 28E      Unit Ltr: P      Location: 990' FSL & 990' FEL

API No. 30-005-60794

Spud Date: 10/28/80  
 TD Date: 03/30/81  
 Comp Date: 05/01/81



Original Perf Details: 2630, 30.5, 31, 37.5, 38, 38.5, 39, 45.5, 46, 46.5  
 8000 gals 28% acid

Jan-88 Added P1: 2624, 25, 28, 29, 33, 34, 35, 36, 40, 41, 48, 49, 50, 51, 52  
 No treatment

Nov-88 Acidized w/ 2500 gals

Mar-01 Tagged fill @ 2569'.

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised March 25, 1999

OIL CONSERVATION DIVISION  
2040 South Pacheco  
Santa Fe, NM 87505

WELL API NO. 30005-60794
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: Twin Lakes San Andres Unit
7. Well No. 86
8. Pool name or Wildcat Twin Lakes; San Andres (Assoc)

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
Oil Well ☐ Gas Well ☐ Other ☐ Injection Well

2. Name of Operator  
Concho Oil & Gas Corp.

3. Address of Operator  
110 W. Louisiana Ste 410; Midland, Tx 79701

4. Well Location  
Unit Letter P : 990 feet from the South line and 990 from the East line  
Section 01 Township 9S Range 28E NMPM Chaves County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)  
3962 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: Clean out & Stimulate <input checked="" type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Concho Oil & Gas Corp. respectfully requests approval to clean out to PBTD & stimulate the Twin Lakes San Andres Unit No. 86 according to the following procedure:

1. TIH w/ packer and test casing to 300#. If ok, proceed.
2. TIH w/ bit, scraper, DC's and work string.
3. Clean out to PBTD @ 2725'.
4. POOH laying down workstring.
5. Test injection string in hole.
6. Contact OCD and run MIT test.
7. Acidize w/ 500 gals xylene and 1500 gals 20% NE w/ xylene w/ produced water.
8. Flow back all load water. (do not swab)
9. Return to injection.



**Wellbore diagram attached.**

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Production Analyst DATE 9-25-01  
Type or print name Terri Stathem Telephone No. 915/683-7443  
(This space for State use)


APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
Conditions of approval, if any:

# TLSAU #86

Formerly - O'Brien E #4

Lease No.: 24988      Dist. No. :      County: Chaves      Field: Twin Lakes San Andres  
 Section: 1      Twsp: 9S      Range: 28E      Unit Ltr: P      Location: 990' FSL & 990' FEL  
 API No. 30-005-60794

Spud Date: 10/28/80  
 TD Date: 03/30/81  
 Comp Date: 05/01/81



Original Perf Details: 2630, 30.5, 31, 37.5, 38, 38.5, 39, 45.5, 46, 46.5  
 8000 gals 28% acid

Jan-88 Added P1: 2624, 25, 28, 29, 33, 34, 35, 36, 40, 41, 48, 49, 50, 51, 52  
 No treatment

Nov-88 Acidized w/ 2500 gals

Mar-01 Tagged fill @ 2569'