

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES DESIRED	
DISTRIBUTION	
SANTA FE	☒
FILE	☒
U.S.G.S.	☐
LAND OFFICE	☐
OPERATOR	☐

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

MAY 5 1981

O. C. D.
ARTESIA, OFFICE

Form C-103
Revised 10-1-78

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - 17 FORM C-103 FOR SUCH PROPOSALS.)

Oil Well ☐

Gas Well ☒

OTHER: _____

Name of Operator

Read & Stevens, Inc /

Address of Operator

P.O. Box 1518, Roswell, NM 88201

Location of Well

Section I 1980 FEET FROM THE South LINE AND 660 FEET FROM

East LINE, SECTION 36 TOWNSHIP 4S RANGE 26E NEPM

Dr. Production (Show whether Oil, RT, GR, etc.)

3897.6' GR

4. Indicate Type of Lease	State ☒ Fee ☐
5. State Oil & Gas Lease No.	
6. Unit Agreement Name	Hernandez Draw Unit
7. Name of Lease Unit	Hernandez Draw Unit
8. Well No.	1
9. Field and pool, or wildcat	Wildcat
10. County	Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
PERMANENTLY ABANDON ☐
ALTER CASING ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

OTHER ☐

Exhibit I proposed or completed operations (if early state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. SEE RULE 1105.

DST #1 interval 6446'-6580'

PTA. Set plugs as follows:

35sx	6450-6550
35sx	5950-6050
35sx	5300-5400
35sx	4350-4450
35sx	3050-3150
35sx	1390-1490
15sx	@ surface

Total 235 sx class "H" com.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

B. Stubbs

Drilling & Production Mgr DATE 5-2-81

W. A. Gressett

SUPERVISOR, DISTRICT II

MAY 07 1981