

6-21-81

Rudy

13 3/8 c 300± Circ

8 5/8 c 1510 Circ

Propose 4 1/2 c 2800 ± w/ TOC c 8 5/8 shoe

TD 5853

PB

WC c 5660 - 100' plug 5600-5700

Abc c 4955 - 100' plug 4900-5000

Gloriette c 2800' - 100' plug 2800±-2900±

Call Rudy
8.2637

Rudy will
check on
Perfs c 2529

Rudy will
tell them
to re file

8 5/8" 1506 - Circ.

4 1/2" 2826 -

TOC-1250

8-1-81

F 2710³⁰⁻⁴⁰ ~~30~~ treat XW CIB 2710 - 35' cement

F 2570³⁰⁻⁴² ~~30~~ - 52-58 -

CIB P-2520 35' "

P 2150²⁰⁹⁰⁻²¹⁰⁵ ~~63~~ -

XW. CIB P-2145 35' "

~~2090-2105~~
25 SX.

2200 -

Cut Pull 4 1/2" ¹²³⁰
~~1200~~ -

spot 255+ @ 2200 - lay @ 2000'

" 35 SX stub

155+ @ surface.

7-27-81 2:50 PM. Rudy -

9:00 AM

9-1-81 Rudy was in and will
tell them to get corrected up again.