

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
ARTESIA, NM 88210

Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM-27909

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Comanche PQ Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Unders. San Andres

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Unit A, Sec. 27-T10S-R25E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3536.1' GR

12. COUNTY OR PARISH

Chaves

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Propose to plug and abandon well as follows:

- 1) Set 50 sx cement plug to cover perfs 944-948' and water protection 750-650', tag plug.
- 2) Set cement plug 50'-surface and set regulation abandonment marker.

NOTIFY BLM, ROSWELL, NM, 24 HOURS IN ADVANCE OF PLUGGING.

Clean location after plugging.



18. I hereby certify that the foregoing is true and correct

SIGNED *[Signature]*

TITLE Production Supervisor

DATE 10-23-86

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED
PETER W. CHESTER

NOV 3 1986

*See Instructions on Reverse Side

