HU. OF COPIC	S PECLIVED		-			Form C-103 Supersedes ()1d	
SAUTA FE NEW MEXICO			EW MEXICO OIL CON	OIL CONSERVATION COMMISSION		C-102 and C-103 Effective 1-1-65	
FILE							
U.S.G.S.			30-0	05-60925		Sa. Indicute Type of Lease State X Fee	
LAND OFFIC	: E					5. State Off & Gas Lesse No.	
						L-5347	
	T USE TRIS FOR	SUNDRY NOTICES	AND REPORTS OF	N WELLS BACK TO A DIFFEREN	RECEIVED	7. Unit Agreement Force	
1. 0'L WELL	GAS VIELL	X OTHER-		FE	B 2 3 1982	Campbell Station Unit	
Carl A. Schellinger						Campbell Station Unit	
1. Altress of O				ART	ESIA, OFFICE	9. Well No.	
		ell, New Mexic	o 88201			1 10. Field and Pool, or Wildoat	
4. Lecation of V	м	660	T FROM THE South	6	60 FEET VROM	Wildcat	
UNIT LETTE	R	FCr	T FROM THE JOU CIT	LINE AND	OU FEET FROM	an a	
THE WE	est	E. SECTION 34	TOWNSHIP 8-S		27-Е ммрм.		
77777777	<u>unn</u> i	<u></u>	Elevation (Show whethe	TUF, KT, GR, ctc.)	12. County	
illiilli		///////////////////////////////////////	3871'GR 3882			Chaves	
16.	·····)	and a star star way to a star a star of the star star star star star star star star	Box To Indicate		ce, Report or Oth	er Data	
	NOTICE	OF INTENTION	TO:	1	SUBSEQUENT	REPORT OF:	
		•	PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING	
TEMPORARILY A	Ē			COMMENCE DRILL	ING OPHS.	PLUG AND ABANDONMENT	
PULL OR ALTER	F		CHANGE PLANS	CASING TEST AND		tion Fourinment	
			[OTHER RIG	Up Dual Compl	etion Equipment [X]	
OTHER			L	,			
	opened of Comp RULE 1103.	pleted Operations (Clea	aly state all pertinent de	etails, and give pert	inent dates, including	estimated date of starting any proposed	
1/26/82	Move in a	und rig up Supe	rior Well Servi	ce completio	n unit and Sta	r Tool Co., reverse pump.	
	Shut in t	ubing pressure	1100 PSI	annulus to	dicoloco dos o	nd kill well Pick un	
	Blow well down, pump 2% KCL water down annulus to displace gas and kill well. Pick up more tubing and run on in hole, tag sand at approx 5500 ft, reverse sand off of RBP,						
	approx 65 ft of sand, circ, hole clean.						
	Release F	Release RBP and pull to approx 5100 ft, above Abo perfs. and secure well for the day at					
1 /07 /00	3:00 P.M.	3:00 P.M. Baker tool man did not have all his equipment. No pressure on wellhead, load and circ. hole w/2% KCL water and wait on Baker Packers.					
1/27/82 No pressure on wellhead, load and circ. hole W/2% KLL water and wait on Baker Pa Baker Packer's man and blast joints show up at 11:00 A.M. Trip out of hole wit						out of hole with RBP.	
	Rig up and run in hole with Baker, Lok - Set Packer, on and off tool, Baker Sliding						
	sleeve (1.87 I.D.) 70 ft. of Baker blast joints and flange up wellhead, w/10,000# of						
1 /00 /00	tension pulled on tubing, as per diagram and talley.						
1/28/82	Swab load water off of Abo perfs through sliding sleeve and up tubing as hard as possible for 10 hours, nothing but water, very little gas.						
1/29/82	Shut in tubing pressure 150 PSI: backside - 200 PSI Swab load water but trying to gas a						
	little. After approx. 6 hours of swabing, well kicks off and starts to flow water on its						
1/30/82	own with gas increasing. Flow well on 3/4" choke until sundown to clean up. Shut in tubing pressure 400 PSI and 700 PSI on annulus. Open well to pit and flare to						
1/30/02	clean up Abo through tubing, gas wet but burning. Flow tries to die, run swab.						
	cont'd o	n attached Exhi	ihit				
18. 1 hereby certify that the information above is true and complete to the best of my knowledge and belief.							
Ki	lout	M. ~ ~	TITLE	perator		DATE 2/10/82	
	110	hanne		SUPERVISOR, DI	(977 D.L. 0	FEB 2 3 1982	
APPROVED BY	NUL	Africal		The DIA CONTRACT	STRICT U	DATE	

CONDITIONS OF APPROVAL, IF ANYL

Exhibit attached nereto and made a part of New Mexico Oil Conservation Commission Form C-103

1/30/82 After approx. 7 hours of flowing through tubing on full open choke, 3/4", well flowing w/5-10 PSI or tubing trying to dry up. Turn annulus to pit on 1/4 (16/64) choke for 1 hour, gas dry holding on 190 to 200 PSI - (est. 300 MCFD) Able to get 1 joint of 1 in. pipe down backside between 8 5/8 and 13 3/8. Mix 100 sks to fill hole and back in cellar. Secure well and shut down for day at 3:00 P.M.
2/1/82 Shut in tubing pressure 700 PSI, annulus pressure 200 PSI. Rig up and go in hole w/Jarrel Services, Inc. to close Baker sleeve, turn Abo up annulus. Sleeve at 5243 ft. ground level, 5253 K.B. Go in hole, pull Eg. pin in blanking plug. Go in hole, pull blanking plug in Lok-Set profile. Flow Penn to Pit to clean up Release all equipment. Well ready for production status.

Diagram of Dual Completion Set-up is attached Penn perfs will be produced through tubing and Abo perfs through the annulus, pursuant to OCD hearing. NOTE: C-102 is also attached to designate SW_4^1 to Abo and S_2^1 to Penn.

Section St. TUBING TUBING WELL NAME olion !! SIZE & NUMBER X FIELD WEIGHT COUNTY GRADE LURS دَ ·Ib F V STATE THREAD Ŕ 41CD P 15 X NEW DATE 252TH 14 u w.o. IOC 6303 13 ITEM DESCRIPTION ESTIMATE 12 Pacher Ы Connecto 81 Proti Ser P X 3 P Tubing 040.40 1 14 -1[5 his lo 117 8 Ø 5177 98 9 20 **A**60 Perfs 10.05 D M 5129 bmg 6 5229 5 SJUZAL 4 5 m \leq 3 S 6 (a' n \overline{a} e P М Is 2 6303 ension pulled 5 Ing ec L 637 Penn Perfs PREPARED FOR ig er PHONE クイ PREPARED OFFICE 263 6381 6023 NAVIGATION BOULEVARD P.O. BOX 3048 • HOUSTON, TEXAS 77001 TELEPHONE (713) 923-9351 • TELEX 76-2833 SION OF BAKER OIL TOOLS GROUP, BAKER INTERNATIONAL CORPORATION