

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.D.B.	
LAND OFFICE	
OPERATOR	

MAY 21 1992

O. C. D.

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
LG-5574

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.OIL WELL ☐ GAS WELL ☒ OTHER: _____

Name of Operator

McKay Oil Corporation

Address of Operator

Post Office Box 2014, Roswell, New Mexico 88201

Location of Well

UNIT LETTER G, 1980 FEET FROM THE North LINE AND 1980 FEET FROM
THE East LINE, SECTION 34 TOWNSHIP 6S RANGE 23E N.M.P.M.

7. Unit Agreement Name

8. Farm or Lease Name

Corn Trust State

9. Well No.

#1

10. Field and Pool, or Wildcat

Wildcat Abo

15. Elevation (Show whether DF, RT, GL, etc.)

4140

12. County

Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

CONFORM REMEDIAL WORK ☐

TEMPORARILY ABANDON ☐

PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐

CHANGE PLANS ☐

OTHER ☐

REMEDIAL WORK ☐

COMMENCE DRILLING OPNS. ☐

CASING TEST AND CEMENT JOBS ☐

OTHER ☐

ALTERING CASING ☐

PLUG AND ABANDONMENT ☒

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

Operator plugged and abandoned well as follows:

1. Set CIBP @ 3120'
2. Set 10 sxs cement plug @ 3120' - 2970'
3. Shoot casing @ 1500'
4. Pull casing
5. Set 24 sxs cement plug to cover 4½" 1550' - 1450'
6. WOC - tag plug
7. Set 25 sxs cement plug 100' to surface
8. Displaced casing w/mud between cement
9. Installed dry hole marker.

TD-4017

Post ID-2
10-9-92
P+H

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

by Theresa Rodriguez TITLE Production Analyst DATE 5-20-92

PROVED BY GW TITLE _____ DATE 12-4-92

CONDITIONS OF APPROVAL, IF ANY: