

Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

dsf up +

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION RECEIVED P.O. Box 2088 Santa Fe, New Mexico 87504-2088

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

NOV 9 '90

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.

5. Indicate Type of Lease STATE FEE

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR TO PLUG BACK TO A DIFFERENT RESERVOIR. USE 'APPLICATION FOR PERMIT' (FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

Drumm Com.

1. Type of Well: OIL WELL GAS WELL OTHER

8. Well No. 1

2. Name of Operator Lynx Petroleum Consultants, Inc.

9. Pool name or Wildcat Buffalo Valley Penn, W.

3. Address of Operator P.O. Box 1979

4. Well Location Unit Letter E : 1980 Feet From The North Line and 660 Feet From The West Line Section 33 Township 14-S Range 26-E NMPM Chaves County

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3447' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data. NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK, PLUG AND ABANDON, TEMPORARILY ABANDON, CHANGE PLANS, PULL OR ALTER CASING, OTHER. SUBSEQUENT REPORT OF: REMEDIAL WORK, ALTERING CASING, COMMENCE DRILLING OPNS., PLUG AND ABANDONMENT, CASING TEST AND CEMENT JOB, OTHER.

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1. Set C.I.B.P. @ ± 6625' and spot 50' of cement on top of C.I.B.P.. Load hole with mud. Plug @ 6002 Penn
2. Cut 4 1/2" casing at ± 4550' and pull out of hole.
3. Spot stub plug 4450'-4650'. Tag stub plug.
4. Spot O.H. plug 2900'-3000'. At Gloria 25.50
5. Spot Shoe plug 1300'-1400'. Tag shoe plug.
6. Spot casing plug 335'-435', and surface plug 0'-50'.
7. Install dry hole marker and clean location.

Notify N.M.O.S.D. in sufficient time to withdraw. Plugging

I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE [Signature] TITLE President DATE 11/8/90 TYPE OR PRINT NAME Marc L. Wise TELEPHONE NO. 392-6950

(This space for State Use) APPROVED BY [Signature] TITLE Drill Geologist DATE 11/17/90 CONDITIONS OF APPROVAL IF ANY: All plugs 250ks or 100' whichever is greater