

clsr

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
 Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Abandoned Drilling Well		5. LEASE DESIGNATION AND SERIAL NO. LC 067811-A
2. NAME OF OPERATOR BERGE EXPLORATION, INC.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME -
3. ADDRESS OF OPERATOR 7100 North Broadway, Ste. 2-D Denver, CO 80221		7. UNIT AGREEMENT NAME -
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FSL 660' FEL Sec. 26-7S-26E		8. FARM OR LEASE NAME Dale Federal
14. PERMIT NO. -		9. WELL NO. 17
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3841' GR		10. FIELD AND POOL, OR WILDCAT O. C. D. w/c ato -
		11. SECTION, T., R., M., OR BLK. AND SURVEY OR AREA Sec. 26-7S-26E
		12. COUNTY OR PARISH Chaves
		13. STATE N.M.

RECEIVED BY
 JUN 18 1986
 O. C. D.
 ARTESIA, OFFICE

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <u>Surface Restoration</u>	<input checked="" type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This is to advise that the pits, well pad and access road of above well have been cleaned, leveled, ripped and seeded.

A joint inspection by Jerry Long, Agent for Berge, and Candace Ojala, BLM, on June 11, 1986, found the surface restoration to comply with Resource Area Abandonment Stipulations. Recent rains in the area should provide ample moisture to assure seed germination.




I hereby certify that the foregoing is true and correct
 SIGNED Jerry H. Long TITLE Agent DATE June 11, 1986
 (This space for Federal or State office use)

APPROVED BY _____ TITLE _____
 CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD
 PETER W. CHESTER
 JUN 13 1986
 BUREAU OF LAND MANAGEMENT
 ROSWELL RESOURCE AREA

*See Instructions on Reverse Side



UNIVERSITY OF TORONTO
LIBRARY
D O C
400-923-3784