

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	<input checked="" type="checkbox"/>
LAND OFFICE	<input checked="" type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

DEC 21-1982

O. C. D.

ARTESIA, OFFICE

5a. Indicate Type of Lease State <input type="checkbox"/> For <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name Newlin-A
9. Well No. 1
10. Field and Pool, or Wildcat Wildcat-SanAndres
12. County Chaves

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Cities Service Company	8. Farm or Lease Name Newlin-A
3. Address of Operator Box 1919 Midland, Texas 79702	9. Well No. 1
4. Location of Well UNIT LETTER B 660 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 14 TOWNSHIP 7S RANGE 29E N.M.P.M.	10. Field and Pool, or Wildcat Wildcat-SanAndres
15. Elevation (Show whether DF, RT, GR, etc.) 3500' GR	12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 3600' Sand, PBTD 3013'. This well was plugged and abandoned in the following manner:

1. MIRU pulling unit. Pulled rods, BHP and tubing.
2. Set a CIPB @ 2875' and dumped 5 sacks cement on top of BP to 2825'.
3. RIH w/OE tubing to 2814'. Circulated hole w/mud laden fluid. Pulled tubing to 2305'.
4. Spotted a 25 sack cement plug 2305-2105'. Pulled tubing to 1827'.
5. Spotted a 25 sack cement plug 1827-1627'. Pulled tubing to 424'.
6. Spotted a 25 sack cement plug 424-224' across the 8-5/8" casing shoe @ 350'.
7. POOH, ND BOP and cut off WH.
8. RIH w tbg to 60'. Spotted a 10 sack surface plug 60' to surface. Installed dry hole marker to designate a plugged and abandoned location.

(Cont. on back of page)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Elmer Startz TITLE Reg. Opr. Mgr. - Prod. DATE 12-16-82  
APPROVED BY Darrell Moore TITLE Geologist DATE 4/1/86  
CONDITIONS OF APPROVAL, IF ANY: