

UNITED STATES **Artesia, NM 88210**  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☒ well other ☐

2. NAME OF OPERATOR

**DEPCO, Inc.**

3. ADDRESS OF OPERATOR

**800 Central, Odessa, TX 79761**

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) **I-1980 FSL & 660 FEL, Sec. 19, T-5-S, AT SURFACE: R-25-E**  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐  
(other) ☐

SUBSEQUENT REPORT OF:

☐  
☒  
☒  
☐  
☐  
☐  
☐  
☐  
☐

**RECEIVED**

**APR 13 1983**

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

**OIL & GAS  
MINERALS MGMT. SERVICE  
ROSWELL, NEW MEXICO**

5. LEASE

**NM 34408**

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME **AUG 11 1983**

8. FARM OR LEASE NAME

**Rosa Federal O. C. D.**

9. WELL NO.

**7**

10. FIELD OR WILDCAT NAME

**Pecos Slopes Abo**

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

**Sec. 19, 5, 25**

12. COUNTY OR PARISH

**Chaves**

13. STATE

**New Mexico**

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

**3840 GR**

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

- 3-29-83: Drld out cmt to 4139' PBTD. Perf w/1 SPF @ 3677-90', 3799-3802', 04-6', 3814-27'.
- 3-30-83: Acidized f/3799-3827' w/3500 gals. 7 1/2% Abo acid w/1000 SCF N<sub>2</sub> p/bbl. Acidized f/3677-3690' w/1750 gals. 7 1/2% Abo acid w/1000 SCF N<sub>2</sub> p/bbl. Flushed w/13,000 SCF-N<sub>2</sub>.
- 3-31-83: Frac w/77,500 gals. YF-4 & CO<sub>2</sub>, 101,000# 20/40 sand & 65,500 # 10/20 sand. Preparing to start testing.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED R.L. Denney **R.L. Denney** TITLE **Chief Prod Clerk** DATE **4-12-83**

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

**ACCEPTED FOR RECORD**

**AUG 9 1983**

## Instructions

**General:** This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

**Item 4:** If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

**Item 17:** Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.