

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☒ well other ☐
2. NAME OF OPERATOR
DEPCO, INC. ✓
3. ADDRESS OF OPERATOR
800 Central, Odessa, Texas 79761
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) **K-1980' FSL & 1680' FWL, Sec. 20,**
AT SURFACE: **T-5S, R-25E**
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

- TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) **Set Csg. & Core**

SUBSEQUENT REPORT OF:

- ☒
☐
☐
☐
☐
☐
☐
☐
☐
☐

RECEIVED

APR 13 1983

OIL & GAS
MINERALS MGMT. SERVICE
ROSWELL, NEW MEXICO

5. LEASE
NM 36408
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
RECEIVED
7. UNIT AGREEMENT NAME
APR 21 1983
8. FARM OR LEASE NAME
Rose Federal **O. C. D.**
9. WELL NO.
81 **ARTESIA, OFFICE**
10. FIELD OR WILDCAT NAME
Pecos Slopes Abo
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 20, 5, 25
12. COUNTY OR PARISH **Chaves** 13. STATE **New Mexico**
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
3821 GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

3-29-83 Drld. 14 3/4" hole to 955'. Ran 24 jts. 10 3/4" 40.50# J-55 csg. set @ 949'. Cmtd. w/500 sxs. Howco Lite w/1/4# floccale & 2% CaCl. p/sx., followed w/200 sxs. Class "C" w/2% CaCl. Circ. 75 sxs. PD @ 3:00 am. Tested pipe & BOP @ 1000# for 30 min. Tested OK.

3-30-83 Cored for 60' from 1006' to 1066'.

4-6-83 Drld. 7 7/8" hole to 4230' TD. Ran 105 jts. 4 1/2" 10.50# J-55 csg. set @ 4229' w/DV tool @ 2300'. Cmtd. w/350 sxs. 50-50 pozmix w/5# salt, 3/10 of 1% CYR-2, 3/10 of 1% Halad 4 p/sx.

4-7-83 Cmtd. 2nd stage w/275 sxs. Howco Lite w/5# salt p/sx., followed w/700 sxs. 50-50 pozmix, w/5# salt p/sx. PD @ 9:30 am. Circ. 27 sxs. WOC.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED R. L. Denney **R. L. Denney** TITLE **Chief Prod Clerk** DATE **4-12-83**

ACCEPTED FOR RECORD (space for Federal or State office use)
(ORIG. SGD.) **DAVID R. GLASS**

APPROVED BY _____ DATE _____
CONDITIONS OF APPROVAL _____

APR 20 1983

ROSWELL, NEW MEXICO

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.