

OIL CONSERVATION DIVISION **RECEIVED**

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

MAR 09 1983

O. C. D.
ARTESIA, OFFICE

Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
State Oil & Gas Lease No.	
LQ 1076	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator
STEVENS OPERATING CORPORATION ✓

Address of Operator
P. O. Box 2408, Roswell, New Mexico 88201

Location of Well
UNIT LETTER **D** **660** FEET FROM THE **North** LINE AND **660** FEET FROM
THE **West** LINE, SECTION **16** TOWNSHIP **7S** RANGE **27E** NMPM.

7. Unit Agreement Name
8. Farm or Lease Name Rua State
9. Well No. 1
10. Field and Pool, or Wildcat Wildcat San Andres
12. County Chaves

15. Elevation (Show whether DF, RT, GR, etc.)
4047 GL

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1603.

2-25-83 Spud at 10:00 a.m. w/12" bit.

3- 2-83 Ran 10 joints 8 5/8" x 24# casing. Set and cement at 428' w/150 sxs Howco Lite and 100 sxs Class "C" w/2% CaCl₂. Circulate 51 sxs. WOC 18 hrs. Pressure up 1000# for 30 minutes logging no pressure decrease.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *San Thompson* TITLE Production Controller DATE March 8, 1983

APPROVED BY *Mark Williams* TITLE OIL AND GAS INSPECTOR DATE MAR 09 1983

CONDITIONS OF APPROVAL, IF ANY: