

UNITED STATES DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
Artesia, NM 88210

Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM 18981

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Robert Federal

9. WELL NO.

1

10. FIELD AND POOL OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 26, T-5-S, R-28-E

12. COUNTY OR PARISH

Chaves

13. STATE

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Pearson-Sibert Oil Co. of Texas

3. ADDRESS OF OPERATOR

901 W. Missouri Ave., Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)  
At surface

2310' FNL & 660' FWL Section 26, T-5-S, R-28-E

14. PERMIT NO.

Original Permit 8-11-83  
Deepening Permit 8-30-84

15. ELEVATIONS (Show whether of, RT, GR, AR)

4223' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Well dry and abandoned 3-14-85.

3-13 & 14-85:

Set the following cement plugs in accordance with instructions from Mr. David Glass with the Bureau of Land Management:

8050' - 7950' - 35 sx.

5910' - 5810' - 35 sx.

4050' - 3950' - 35 sx.

2123' - 2220' - 35 sx.

10-sack plug at surface

Set dry hole marker.

11-85:

Location cleaned. Dug pits to bury mud and caliche. Covered caliche pad. Ripped up road and sowed grass seed. Surface restoration completed 11-26-85.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Vice President

DATE 8-25-86

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

Approved as to plugging of the well bore.  
Liability under bond is retained until  
surface restoration is completed.

APPROVED  
PETER W. CHESTER

JAN 30 1987

\*See Instructions on Reverse Side  
BUREAU OF LAND MANAGEMENT  
ROSWELL RESOURCE AREA