

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	<input checked="" type="checkbox"/>
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
LG 6682

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> P&A
Name of Operator		7. Unit Agreement Name
Yates Petroleum Corporation		8. Farm or Lease Name
Address of Operator		Bajillo Draw WQ State
207 South 4th St., Artesia, NM 88210		9. Well No.
Location of Well		5
UNIT LETTER E 1980 FEET FROM THE North LINE AND 660 FEET FROM		10. Field and Pool, or Wildcat
THE West LINE, SECTION 27 TOWNSHIP 7S RANGE 23E N.M.P.M.		Und. Pecos Slope Abo
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
3898.9' GR		Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged well as follows:

Set CIBP at 3490'. Spotted 20 sacks Class "C" on CIBP. Spot 20 sack plug from 2880-2780'. Spotted 20 sack plug from 1150-980'. Spotted 15 sacks plug to surface. Installed dry hole marker. Cleaned location.

Verbal approval for plugging given by Mr. Larry Brooks, NMOCD, Artesia, 11-22-83.

3. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

APPROVED BY Johnnie Robinson TITLE Production Supervisor DATE 12-7-83

APPROVED BY Johnnie Robinson TITLE OIL AND GAS INSPECTOR DATE 1-23-90

CONDITIONS OF APPROVAL, IF ANY: MS