


STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	<input type="checkbox"/>
LAND OFFICE	<input type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501



Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator Rhymes Drilling Co., Inc. ✓ 3. Address of Operator P.O. Box 729, Roswell, NM 88201 4. Location of Well UNIT LETTER C, 990' FEET FROM THE North LINE AND 1650' FEET FROM THE West LINE, SECTION 19 TOWNSHIP 8South RANGE 29 East NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 3985.7 Gr	7. Unit Agreement Name 8. Farm or Lease Name O'Brien "19" 9. Well No. #2 10. Field and Pool, or Wildcat Twin Lakes SA Assoc. 12. County Chaves
--	--

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10/25/83 - Pull rods and tubing
Perforate @ 2687.5, 2688, 2689, 2690, 2691, 2697, 2698, 2699, 2700, 2701 & 2702
Eleven shots - one hole per foot
10/26/83 - Acidize with 4000 gallons 28% NEFE
10/27/83 - Put on pump

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Judith Mitchell TITLE Production Clerk DATE 10/27/83

APPROVED BY Mike Williams TITLE OIL AND GAS INSPECTOR DATE NOV 08 1983

CONDITIONS OF APPROVAL, IF ANY: