			015/
Submit 3 Copies	State of Nov	. Maria	C_{1}
To Appropriate	State of New Energy, Minerals and Natura		Form C-103 Revised 1-1-89
District Office	Energy, witherars and Natura	ar Resources Department	Revised 1-1-89
DISTRICT I	OIL CONSERVAT	TON DIVISION	WELL API NO.
P.O. Box 1980, Hobbs, NM 88240		Pacheco 3031-12345	30-005-62055
	Santa Fe, NM	4 8759 59	630-005-62055
DISTRICT II		/ % / / / / / / / / / / / / / / / / / / /	Indicate Type of Lease
811 South First, Artesia NM 88210			STATE - (X) FEE
DISTRICT III		OCD RECEIVED	15 - State Oil & Gas Lease No.
1000 Rio Brazos Rd., Aztec, NM 87410		ARTESIA	15 State Oil & Gas Lease No.
			₩/VA1047
SUNDRY NOTIC	ES AND REPORTS ON V	WELL'S &	Lease Name or Unit Agreement
(DO NOT USE THIS FORM FOR PROPO	OSALS TO DRILL OR TO DEEPH	EN OR PLUCIBACE TO AL	Name:
DIFFERENT RESERVOIR. USE "AF	PROPOSALS	RM C-101) FOR SUCH	
13. Type of Well:	The obtain		West Elida Unit
	as Well	Other	West Enda ont
14. Name of Operator			14. Well No.
Prairie Sun, Inc.			1
15. Address of Operator			15. Pool name or Wildcat
los ridacos or operator			13. Poor name or windcat
P. O. Box 8280 Roswell, NM 8820	2-8280 /2/- 2/	-29	Wildcat
16. Well Location	7		
Unit letter <u>C</u> :	660 feet from the North		feet from the West line
	13. Elevation (Show whether DF, 4726' GR	RKB, RT, GR, etc.	
	4720 GR		
Check As		Nature of Notice Repo	art or Other Data
	opropriate Box to Indicate		
NOTICE OF INTENTI	opropriate Box to Indicate ON TO:	SUBSEQUENT	TREPORT OF:
NOTICE OF INTENTI	opropriate Box to Indicate	SUBSEQUENT	
NOTICE OF INTENTI REMEDIALWORK PLUG A	opropriate Box to Indicate ON TO: AND ABANDON REMEDIAL	SUBSEQUENT	TREPORT OF:
NOTICE OF INTENTI REMEDIALWORK PLUG A ()	opropriate Box to Indicate ON TO: AND ABANDON REMEDIAL ()	SUBSEQUENT	TREPORT OF:
NOTICE OF INTENTI REMEDIALWORK PLUG A ()	opropriate Box to Indicate ON TO: AND ABANDON REMEDIAL ()	SUBSEQUENT WORK	T REPORT OF: ALTERING CASING ()
NOTICE OF INTENTI REMEDIALWORK PLUG A () TEMPORARILY ABANDON CHANG ()	ppropriate Box to Indicate ON TO: AND ABANDON REMEDIAL () GE PLANS COMMENC ()	SUBSEQUENT . WORK () CE DRILLING OPNS. ()	T REPORT OF: ALTERING CASING ()
NOTICE OF INTENTI REMEDIALWORK PLUG A () TEMPORARILY ABANDON () PULL OR ALTER CASING ()	ppropriate Box to Indicate ON TO: AND ABANDON REMEDIAL () GE PLANS COMMENC ()	SUBSEQUENT . WORK () CE DRILLING OPNS.	T REPORT OF: ALTERING CASING ()
NOTICE OF INTENTI REMEDIALWORK PLUG A () TEMPORARILY ABANDON CHANG ()	ppropriate Box to Indicate ON TO: AND ABANDON REMEDIAL () GE PLANS COMMENC () CASING TE	SUBSEQUENT . WORK () CE DRILLING OPNS. ()	T REPORT OF: ALTERING CASING ()
NOTICE OF INTENTI REMEDIALWORK PLUG A () TEMPORARILY ABANDON () PULL OR ALTER CASING () OTHER:	ppropriate Box to Indicate ON TO: AND ABANDON REMEDIAL () GE PLANS COMMENC () CASING TE	SUBSEQUENT WORK CE DRILLING OPNS. () EST AND CEMENT JOB Continued Operations	PLUG & ABAND.
NOTICE OF INTENTI REMEDIALWORK PLUG A () TEMPORARILY ABANDON () PULL OR ALTER CASING ()	ppropriate Box to Indicate ON TO: AND ABANDON REMEDIAL () GE PLANS COMMENC () CASING TE	SUBSEQUENT WORK CE DRILLING OPNS. () EST AND CEMENT JOB Continued Operations	PLUG & ABAND.
NOTICE OF INTENTI REMEDIALWORK PLUG A () TEMPORARILY ABANDON () PULL OR ALTER CASING () OTHER: 15. Describe proposed or completed operations are already as a second completed operation.	ppropriate Box to Indicate ON TO: AND ABANDON REMEDIAL () GE PLANS COMMENC () CASING TE	SUBSEQUENT WORK CE DRILLING OPNS. () EST AND CEMENT JOB Continued Operations	PLUG & ABAND.
NOTICE OF INTENTI REMEDIALWORK PLUG A () TEMPORARILY ABANDON CHANG () PULL OR ALTER CASING () OTHER: 15. Describe proposed or completed operat proposed work). SEE RULE 1103. 11-23-98 thru 11-25-98	ppropriate Box to Indicate ON TO: AND ABANDON REMEDIAL () GE PLANS COMMENC () CASING TE OTHER: dions. (Clearly state all pertinent de	SUBSEQUENT WORK () CE DRILLING OPNS. () EST AND CEMENT JOB Continued Operations tails, and give pertinent dates, in	PLUG & ABAND. () including estimated date of starting any
NOTICE OF INTENTI REMEDIALWORK PLUG A () TEMPORARILY ABANDON CHANG () PULL OR ALTER CASING () OTHER: 15. Describe proposed or completed operat proposed work). SEE RULE 1103. 11-23-98 thru 11-25-98 Move in and rig up Real Well Service	ppropriate Box to Indicate ON TO: AND ABANDON REMEDIAL () GE PLANS COMMENC () CASING TE OTHER: cions. (Clearly state all pertinent de	SUBSEQUENT L WORK () CE DRILLING OPNS. () EST AND CEMENT JOB : Continued Operations tails, and give pertinent dates, in	PLUG & ABAND. () PLUG & ABAND. () including estimated date of starting any
NOTICE OF INTENTI REMEDIALWORK PLUG A () TEMPORARILY ABANDON CHANG () PULL OR ALTER CASING () OTHER: 15. Describe proposed or completed operat proposed work). SEE RULE 1103. 11-23-98 thru 11-25-98 Move in and rig up Real Well Service collars and go in hole. Pick up tubing ar	propriate Box to Indicate ON TO: AND ABANDON REMEDIAL () GE PLANS COMMENC () CASING TE OTHER: Cons. (Clearly state all pertinent de	SUBSEQUENT WORK () CE DRILLING OPNS. () EST AND CEMENT JOB Continued Operations tails, and give pertinent dates, in the continuent of the continuent	PLUG & ABAND. () PLUG & ABAND. () including estimated date of starting any e up 7 7/8" bit, 8—4.75" drill ad bit locked up. Circulate hole
NOTICE OF INTENTI REMEDIALWORK PLUG A () TEMPORARILY ABANDON CHANG () PULL OR ALTER CASING () OTHER: 15. Describe proposed or completed operat proposed work). SEE RULE 1103. 11-23-98 thru 11-25-98 Move in and rig up Real Well Service collars and go in hole. Pick up tubing ar with clean water. Pull out of hole and la	ppropriate Box to Indicate ON TO: AND ABANDON REMEDIAL () GE PLANS COMMENC () CASING TE OTHER: cions. (Clearly state all pertinent de e pulling unit. Move in and rig and tag at 2630'. Pick up swivel y down drill collars and bit. Bit	SUBSEQUENT WORK () CE DRILLING OPNS. () EST AND CEMENT JOB Continued Operations tails, and give pertinent dates, in the continuent of the continuent	PLUG & ABAND. () PLUG & ABAND. () including estimated date of starting any e up 7 7/8" bit, 8—4.75" drill ad bit locked up. Circulate hole
NOTICE OF INTENTI REMEDIALWORK PLUG A () TEMPORARILY ABANDON CHANG () PULL OR ALTER CASING () OTHER: 15. Describe proposed or completed operat proposed work). SEE RULE 1103. 11-23-98 thru 11-25-98 Move in and rig up Real Well Service collars and go in hole. Pick up tubing ar	ppropriate Box to Indicate ON TO: AND ABANDON REMEDIAL () GE PLANS COMMENC () CASING TE OTHER: cions. (Clearly state all pertinent de e pulling unit. Move in and rig and tag at 2630'. Pick up swivel y down drill collars and bit. Bit	SUBSEQUENT WORK () CE DRILLING OPNS. () EST AND CEMENT JOB Continued Operations tails, and give pertinent dates, in the continuent of the continuent	PLUG & ABAND. () PLUG & ABAND. () including estimated date of starting any e up 7 7/8" bit, 8—4.75" drill ad bit locked up. Circulate hole
NOTICE OF INTENTI REMEDIALWORK PLUG A () TEMPORARILY ABANDON CHANG () PULL OR ALTER CASING () OTHER: 15. Describe proposed or completed operat proposed work). SEE RULE 1103. 11-23-98 thru 11-25-98 Move in and rig up Real Well Service collars and go in hole. Pick up tubing ar with clean water. Pull out of hole and la Rig down and release pulling unit and re	propriate Box to Indicate ON TO: AND ABANDON REMEDIAL () GE PLANS COMMENC () CASING TE OTHER: cions. (Clearly state all pertinent de de pulling unit. Move in and right tag at 2630'. Pick up swivel by down drill collars and bit. Bit ental equipment on 11-25-98. We	SUBSEQUENT WORK () EE DRILLING OPNS. () EST AND CEMENT JOB Continued Operations tails, and give pertinent dates, in the preverse equipment. Make and drill cement to 2790° are thad piece of steel wedged yell shut in with BOP.	PLUG & ABAND. () PLUG & ABAND. () including estimated date of starting any e up 7 7/8" bit, 8—4.75" drill ad bit locked up. Circulate hole
NOTICE OF INTENTI REMEDIALWORK PLUG A () TEMPORARILY ABANDON CHANG () PULL OR ALTER CASING () OTHER: 15. Describe proposed or completed operat proposed work). SEE RULE 1103. 11-23-98 thru 11-25-98 Move in and rig up Real Well Service collars and go in hole. Pick up tubing ar with clean water. Pull out of hole and la Rig down and release pulling unit and re	ppropriate Box to Indicate ON TO: AND ABANDON REMEDIAL () GE PLANS COMMENC () CASING TE OTHER: cions. (Clearly state all pertinent de e pulling unit. Move in and rig and tag at 2630'. Pick up swivel y down drill collars and bit. Bit	SUBSEQUENT WORK () EE DRILLING OPNS. () EST AND CEMENT JOB Continued Operations tails, and give pertinent dates, in the preverse equipment. Make and drill cement to 2790° are thad piece of steel wedged yell shut in with BOP.	PLUG & ABAND. () PLUG & ABAND. () including estimated date of starting any e up 7 7/8" bit, 8—4.75" drill ad bit locked up. Circulate hole
NOTICE OF INTENTI REMEDIALWORK PLUG A () TEMPORARILY ABANDON CHANG () PULL OR ALTER CASING () OTHER: 15. Describe proposed or completed operat proposed work). SEE RULE 1103. 11-23-98 thru 11-25-98 Move in and rig up Real Well Service collars and go in hole. Pick up tubing ar with clean water. Pull out of hole and la Rig down and release pulling unit and relea	propriate Box to Indicate ON TO: AND ABANDON REMEDIAL () GE PLANS COMMENC () CASING TE OTHER: dions. (Clearly state all pertinent de e pulling unit. Move in and rig and tag at 2630'. Pick up swivel by down drill collars and bit. Bir ental equipment on 11-25-98. We true and complete to the best of my	SUBSEQUENT WORK () CE DRILLING OPNS. () EST AND CEMENT JOB Continued Operations tails, and give pertinent dates, in the preverse equipment. Make and drill cement to 2790' are than piece of steel wedged in the pi	PLUG & ABAND. () PLUG & ABAND. () including estimated date of starting any e up 7 7/8" bit, 8—4.75" drill ad bit locked up. Circulate hole in teeth. Clear metal out of bit.
NOTICE OF INTENTI REMEDIALWORK PLUG A () TEMPORARILY ABANDON CHANG () PULL OR ALTER CASING () OTHER: 15. Describe proposed or completed operat proposed work). SEE RULE 1103. 11-23-98 thru 11-25-98 Move in and rig up Real Well Service collars and go in hole. Pick up tubing ar with clean water. Pull out of hole and la Rig down and release pulling unit and results of the proposed with the proposed of the	propriate Box to Indicate ON TO: AND ABANDON REMEDIAL () GE PLANS COMMENC () CASING TE OTHER: cions. (Clearly state all pertinent de de pulling unit. Move in and right tag at 2630'. Pick up swivel by down drill collars and bit. Bit ental equipment on 11-25-98. We	SUBSEQUENT WORK () EE DRILLING OPNS. () EST AND CEMENT JOB Continued Operations tails, and give pertinent dates, in the preverse equipment. Make and drill cement to 2790° are thad piece of steel wedged yell shut in with BOP.	PLUG & ABAND. () PLUG & ABAND. () including estimated date of starting any e up 7 7/8" bit, 8—4.75" drill ad bit locked up. Circulate hole in teeth. Clear metal out of bit. DATE 11-30-98
NOTICE OF INTENTI REMEDIALWORK PLUG A () TEMPORARILY ABANDON CHANG () PULL OR ALTER CASING () OTHER: 15. Describe proposed or completed operat proposed work). SEE RULE 1103. 11-23-98 thru 11-25-98 Move in and rig up Real Well Service collars and go in hole. Pick up tubing ar with clean water. Pull out of hole and la Rig down and release pulling unit and release pulling unit and results. SIGNATURE Type or print name Gene Lee	propriate Box to Indicate ON TO: AND ABANDON REMEDIAL () GE PLANS COMMENC () CASING TE OTHER: cons. (Clearly state all pertinent de e pulling unit. Move in and rig nd tag at 2630'. Pick up swivel by down drill collars and bit. Bit ental equipment on 11-25-98. We true and complete to the best of my TITLE	SUBSEQUENT WORK () CE DRILLING OPNS. () EST AND CEMENT JOB Continued Operations tails, and give pertinent dates, in the preverse equipment. Make and drill cement to 2790' are than piece of steel wedged in the pi	PLUG & ABAND. () PLUG & ABAND. () including estimated date of starting any e up 7 7/8" bit, 8—4.75" drill ad bit locked up. Circulate hole in teeth. Clear metal out of bit.
NOTICE OF INTENTI REMEDIALWORK PLUG A () TEMPORARILY ABANDON CHANG () PULL OR ALTER CASING () OTHER: 15. Describe proposed or completed operat proposed work). SEE RULE 1103. 11-23-98 thru 11-25-98 Move in and rig up Real Well Service collars and go in hole. Pick up tubing ar with clean water. Pull out of hole and la Rig down and release pulling unit and release pulling unit and results. SIGNATURE Type or print name Gene Lee	propriate Box to Indicate ON TO: AND ABANDON REMEDIAL () GE PLANS COMMENC () CASING TE OTHER: Total tag at 2630'. Pick up swivel by down drill collars and bit. Bit and and equipment on 11-25-98. We see the properties of the desired and complete to the best of my TITLE	SUBSEQUENT WORK () EE DRILLING OPNS. () EST AND CEMENT JOB Continued Operations tails, and give pertinent dates, in the preverse equipment. Make and drill cement to 2790' are than the piece of steel wedged with	PLUG & ABAND. () PLUG & ABAND. () including estimated date of starting any e up 7 7/8" bit, 8—4.75" drill ad bit locked up. Circulate hole in teeth. Clear metal out of bit. DATE 11-30-98 Telephone No. 505-622-7355
NOTICE OF INTENTI REMEDIALWORK PLUG A () TEMPORARILY ABANDON CHANG () PULL OR ALTER CASING () OTHER: 15. Describe proposed or completed operat proposed work). SEE RULE 1103. 11-23-98 thru 11-25-98 Move in and rig up Real Well Service collars and go in hole. Pick up tubing ar with clean water. Pull out of hole and la Rig down and release pulling unit and release pulling unit and results. SIGNATURE Type or print name Gene Lee	propriate Box to Indicate ON TO: AND ABANDON REMEDIAL () GE PLANS COMMENC () CASING TE OTHER: Total tag at 2630'. Pick up swivel by down drill collars and bit. Bit and and equipment on 11-25-98. We see the properties of the desired and complete to the best of my TITLE	SUBSEQUENT WORK () CE DRILLING OPNS. () EST AND CEMENT JOB Continued Operations tails, and give pertinent dates, in the preverse equipment. Make and drill cement to 2790' are than piece of steel wedged in the pi	PLUG & ABAND. () PLUG & ABAND. () including estimated date of starting any e up 7 7/8" bit, 8—4.75" drill ad bit locked up. Circulate hole in teeth. Clear metal out of bit. DATE 11-30-98 Telephone No. 505-622-7355

Conditions of approval, if any:

DATE <u>/2 - 7 -</u> 98



