

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

ALL OIL CONES. COMMISSION
Drawers DD
Permit in Trip
Other Instructions
Page 1 of 1
88210

Form approved
Budget Bureau No. 1004-1
Expires August 31, 1985

4/5

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. NAME OF OPERATOR
McClellan Oil Corporation

3. ADDRESS OF OPERATOR
P.O. Drawer 730, Roswell, NM 88202

4. LOCATION OF WELL (Report location clearly and in accordance with State requirements.
See also space 17 below.)
At surface
1980' FNL & 660' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3614' G.L.

RECEIVED BY
FEB 20 1987
O. C. D.
ARTESIA, OFFICE

5. LEASE DESIGNATION AND SERIAL NO.
NM-0559993

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
MM Comm Fed. Comm.

9. WELL NO.
2

10. FIELD AND POOL OR WILDCAT
South Pecos Slope - Ato

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 35-T9S-R25E

12. COUNTY OR PARISH
Chaves

13. STATE
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)	<input type="checkbox"/>	(Other)	<input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plugged and abandoned as follows:

7-31-86

1. Set 30 sx Class C with 2% CaCl₂ cement plug inside 4-1/2" casing at 4300'. WOC 2 hours. Tagged plug at 4157'.
2. Set 30 sx Class C cement plug from 1565' to 1665'.
3. Set 30 sx Class C cement plug from 957' to 1060'.
4. Set 60' surface plug. Installed dry hole marker. Heavy mud was placed between plugs. All casing was left in the hole. Location has been cleared of equipment and will be cleaned, leveled and ripped per surface abandonment stipulations.



Post ID-2
9-19-86
p+7

18. I hereby certify that the foregoing is true and correct

SIGNED Paul Ragsdale TITLE Paul Ragsdale DATE 8/29/86

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____

CONDITIONS OF APPROVAL, IF ANY: Approved as to plugging of the well bore, Liability under bond is retained until surface restoration is completed.
*See Instructions on Reverse Side

APPROVED
DATE
PETER W. CHESTER
FEB 11 1987
BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA