

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30005-62070
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input checked="" type="checkbox"/> Injection		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Concho Oil & Gas Corp.		6. State Oil & Gas Lease No.
3. Address of Operator 110 W. Louisiana Ste 410; Midland, Tx 79701		7. Lease Name or Unit Agreement Name: Twin Lakes San Andres Unit
4. Well Location Unit Letter <u>F</u> : <u>2310</u> Feet from the <u>NORTH</u> line and <u>2310</u> feet from the <u>WEST</u> line Section <u>25</u> Township <u>8S</u> Range <u>28E</u> NMPM Chaves County		7. Well No. 1
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3930.2 GR		8. Pool name or Wildcat Twin Lakes; San Andres (Assoc)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Concho Oil & Gas Corp. respectfully request approval to plug & abandon the Twin Lakes San Andres Unit No. 1 according to the following procedure:

1. Notify NMOCD Artesia 24 hrs prior to commencement of procedure.
2. Set 170' plug @ 2480-2650' — ~~TA9~~
3. Circ hole w/ mud.
4. Set 100' plug @ 1905-2005'.
5. Cut csg @ 1545' & POOH.
6. Set 100' cmt plug @ 1495-1595'. WOC & tag.
7. Set 100' plug @ ~~820-920'~~ **750'-850'**
8. Circ cmt from 177' to surface.
9. Cut off wellhead & install dry hole marker.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terri Statnem TITLE Production Analyst DATE 10-18-01


Type or print name Terri Statnem Telephone No. 915/683-7413
(This space for State use)
APPROVED BY [Signature] TITLE Wildcat DATE 11-13-01
Conditions of approval, if any:

TLSAU #1

Formerly - O'Brien F #9

Lease No.: 24988 Dist. No. : County: Chaves Field: Twin Lakes San Andres
 Section: 25 Twsp: 8S Range: 28E Unit Ltr: F Location: 2310' FNL & 2310' FWL
 API No. 30-005-62070

Spud Date: 12/20/83
 TD Date: 12/23/83
 Comp Date: 01/23/84



Original Perf Details: P1: 2590, 90.5, 91, 94, 94.5, 95, 98.5, 99, 99.5, 2600, 00.5, 01, 08, 08.5, 09, 09.5, 12.5, 13, 13.5, 14, 18, 19, 20
 7500 gals 28% acid

Jun-89 Add P1: 2580, 81, 82, 84, 85, 86, 88, 89, 92, 93, 96, 97, 2603, 06, 15, 16, 17, 22, 23
 No treatment