- - -		OIL CONS. awer DD	COMMIDDIO	<b>D</b> .		c15
ECEIVED BY	TÅ T	tesia, NM	88210		Approved. et Bureau No. 42–	R1424
	UNITED STATES		5. LEASE NM-13	2078		
AY 07 1985 DE	GEOLOGICAL SURVEY				OR TRIBE NAM	IE
	OFICES AND REPORTS ON		7. UNIT AG	REEMENT NA	AME	
reservoir. Use Form 9-	-331-C for such proposals.)			R LEASE NAM		
	vell 🗆 other Dry		9. WELL N	<u>n Federal</u> o.		
2. NAME OF OPERATOR			3			•···•• 4
<u>McClellan Oil Corporation</u>			10. FIELD OR WILDCAT NAME Pecos Slope Abo			
P.O. Drawe	er 730, Roswell, NM 88202 WELL (REPORT LOCATION CLEARLY.		11. SEC., T. AREA		LK. AND SURV	EY OR
AT SURFACE: AT TOP PROD AT TOTAL DEF			12. COUNTY Chave	OR PARISH		
	DPRIATE BOX TO INDICATE NATURE	OF NOTICE	14. API NO.			
REPORT, OR (	OTHER DATA		15. ELEVAT 3664 '		DF, KDB, ANI	D WD)
REQUEST FOR AP TEST WATER SHU FRACTURE TREAT SHOOT OR ACIDIZ REPAIR WELL PULL OR ALTER ( MULTIPLE COMPLI CHANGE ZONES ABANDON* (other)		PORT OF.	(NOTE: Repo chan	irt results of mu ge on Formi9–3	Itiple completion	or zone
including estin measured and	OPOSED OR COMPLETED OPERATION nated date of starting any proposed we true vertical depths for all markers and ged and Abandoned as follo	ork. If well is di I zones pertinent	rectionally dril	led, give subs	give pertinent' surface location	dates s and
10/30/84:	Circulated hole w/ brine of CIBP at 4100'.	mud. Set	25 sx C1	ass C at	4100' on t	
11/01/84:	Shot off casing at 3095 Set 25 sx plug at 3150'. Set 25 sx plug at 1760'. Set 25 sx plug at 1000'. Set 25 sx plug at surfac	Tagged T	0C at 860			Post # D-2 2- 8-85 2- 8+A
Subsurface Safety V	/alve: Manu, and Type	· ·			<u>a</u>	Ft.
18. I hereby certify	That the foregoing is true and correct			,	/	
SIGNED	L'Kepdale TITLE OPI	erations Mo	Jr DATE	12/12/	84	
APPROVED BY		deral or State offic			PPROVED	ER
CONDITIONS OF APPI	NUVAL, IF ANT:			МА	<b>Y 3</b> 1985	
	*See Instructi	ons on Reverse Si	de	BUREAU OF ROSWELI	LAND MANA( L RESOURCE /	GEMENT AREA