Submit 3 Copies To Appropriate District	State of N	lew Mexico	Form C-103
Office District I	Energy, Minerals a	nd Natural Resources	Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.
<u>District II</u> 811 South First, Artesia, NM 88210	OIL CONSERVATION DIVISION		30-005-62185
District III	strict III 1220 South St. Francis Dr.		5. Indicate Type of Lease STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe,	NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM			LG-5230
87505	TICES AND REPORTS ON	WELLS	7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROP	OSALS TO DRILL OR TO DEEP	EN OR PLLIG BACK TO A	7. Lease Paine of Oliverigicement Paine.
DIFFERENT RESERVOIR. USE "APPI	LICATION FOR PERMIT" (FORM	STENENSON S	South Dallas
PROPOSALS.)	/20		
DIFFERENT RESERVOIR. USE "APPI PROPOSALS.) 1. Type of Well: Oil Well Gas Well 5	Other \	T G	
2. Name of Operator	(4	MAR 2002	7. Well No.
Yates Petroleum Corp	$ \frac{m}{2} $	RECEIVED	#1
3. Address of Operator	15	OCD - ARTESIA	8. Pool name or Wildcat
	esia, NM 88210 🛚 🗽	,	Undes Foor Ranch Wolfcamp
	10	Os a sibility	Gas
4. Well Location		OE 65.8212.82.20	
Unit Letter F :	1980 feet from the N	lorth line and 1980	feet from the West line
	- 100 T	0/5	ATACOM Chaves County
Section 2		Range 26E hether DR, RKB, RT, GR, et	NMPM Chaves County
	10. Elevation (Snow wi	3843' GR	(C.)
11 Charles	Appropriate Box to Ind		Report or Other Data
	INTENTION TO:	SHE	SSEQUENT REPORT OF:
			ALTERING
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR	\square CASING \square
TEMPORARILY ABANDON [CHANGE PLANS	COMMENCE DR	ILLING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING [MULTIPLE COMPLETION	CASING TEST A	ND [7]
OTHER:		OTHER: perfora	ate, acidize
	onerations (Clearly state a		pertinent dates, including estimated date of
starting any proposed work). SE	E RULE 1103. For Multiple	e Completions: Attach well	bore diagram of proposed completion or
recompilation.	1	•	
2/19/02 - MIRU pulling unit.			
2/20/02 – TOH with packer.			
2/22/02 – Perforate Penn 59			tal of 120 holes, .42".
Acidize perfs 5996-60861 wi			
3/1/02 Set CIBP at 5900', a			
Perforate Wolfcamp 5620-5			
3/4/02 Acidize perfs 5620-		6 IC HCL.	
3/5/02 Rig down, turn we	ii to production.		
			·
I hereby certify that the informa	tion above is true and comple	ete to the best of my knowle	edge and belief.
1	//	·	
SIGNATURE SILVE I	TITL	E Engineering Tec	chnician DATE March 11, 2002
Type or print name Susan	Herpin		Telephone No. 505-748-1471
(This space for State use)	ORIGINAL SIGNED BY T		
	SISTECT IS SUPERVISO		DATE WR 15 20
APPPROVED BY		TITLE	DATE DATE
Conditions of approval, if any:			