STATE OF NEW ME						
ERGY AND MINERALS DE	•	LCONSERV	ATION DIVI	SION		
DISTRIBUTION	1	CEIVED BY		3.01		Form C-103
SANTAFE	T	SANTA FE, NE	WMEXICO 87	501		Revised 19-1-2
/100	4 M	NV 10 1097			Sa. Indicate l'y	
LAND OFFICE	1111	AY 19 1987			State	Foo [X]
OPERATOR		O. C. D.			5. State Oil & C	ius Leuse No.
		RTESIA, DEFICE			mmm	mmmm
IDO NOT USE THES FORM		OR TO DEEPEN OF PLU	IG BACK TO A DIFFERENT	MESERVOIR.		
υ 5 ( **	APPLICATION FOR PERMIT -	" (FORM C-101) FOR	SUCH PROPOSACS.		7, Unit Agreeme	nt Name
MELL X WELL	OTHER.					
. me of Operator		,			8, Farm or Leas	
Stevens Operat	ing Corporation	vi			O'Brei	1 R
Address of Operator	23 27 0	0001			9. Well No.	2
	Roswell, NM 8	8201			10 File mate	ool, or WildcatSan
Location of Well	660	East.	1	980		Rigde -Andres
UMIT LETTER	660	FROM THE	LINE AND	FEET FROM	mmm <sup>*</sup>	mmmn
rnSouth cin	21	89		29E		
THEOQUUII LIN					VIIIIII	
	15. E	levation (Show wheth	her DF, RT, GR, etc.)		12. County	
		3957	.5 GR		Chaves	
	Check Appropriate I		Nature of Notic	e, Report or Ot	her Data	
NOTICE	E OF INTENTION TO	D:		SUBSEQUEN	T REPORT OF	:
		PLUG AND ABANDON	71		ALTE	RING CASING
CAPORM REMEDIAL WORK		PLUC AND ABANDON []	REMEDIAL WORK	HC 08H3		AND ABANDONMENT
LL OR ALTER CASING		CHANGE PLANS	CASING TEST AND	7		
SEC ON ACTEN CASING			OTHER			
OTHER						
on the casing cement 50' bel cement surface	set a 4½" CIBP @ , cut and pull o low and 50' abov e plug and set d pluq e 315 as per 4es	ut of the hole the $4\frac{1}{2}$ " stu	le. We would ub and then ta	load the hol	e with mud,	then run
. I hereby certify they the info	ermation above in true and	Complete to the bea	t of my knowledge and Production Ma		DATE	-18-87
mike	Western	71716 L	uil and gas i	INSPECTOR	DAYE MA	Y 2 2 1987

MAY 2 2 1987