State of New Mexico Energy. ierals and Natural Resources Departmen

Form C-103

DISTRICTI P.O. Box 1980, Hobbs, NM 88240

CONDITIONS OF APPROVAL, IP ANY:

OIL CONSERVATION DIVISION

P.O. Box 2088

| t | Revised 1-1-89 |
|-----|---|
| | WELL API NO. 30-005-62201 |
| | 5 Indicate Type of Lease |
| | STATE FEE 6. State Oil & Gas Lease No. |
| _ | |
| | 7. Lease Name or Unit Agreement Name |
| | SALLIE |
| | 8. Well No. |
| | 9. Pool name or Wildcat RACETRACK SA |
| 60 | Feet From TheEast Line |
| | NMPM CHAVES County |
| | |
| | ALTERING CASING GOPNS. PLUG AND ABANDONMENT EMENT JOB |
| clu | ding estimated date of starting any proposed Post ID-2 3-28-97 P41 |
| | |
| | 500 g 0 1387 |
| | |
| | |
| | DATE 2/18/97 |

DISTRICT II Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210 DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: WELL OIL GAS Dry Hole WELL OTHER 2. Name of Operator CIBOLA ENERGY CORPORATION Address of Operator P O BOX 1345, ARTESIA, NM 88210 4. Well Location Unit Letter __ I : 1980 Feet From The _ South Line and 30 28E Township 10S Section Range 10. Elevation (Show whether DF, RKB, RT, GR, etc., 3724.9' GL Check Appropriate Box to Indicate Nature of Notice 11. NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK **TEMPORARILY ABANDON CHANGE PLANS** COMMENCE DRIL **PULL OR ALTER CASING CASING TEST AN** OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1103. Plugged and abandoned well as follows: Plugged 2145'-2285' 40 Sacks Class C Cement Tagged Plug at 2065' Plugged 1540'-1640' 25 sacks cement Set plug at top of San Andres 1570' Plugged 1000'-1100' 25 sacks cement Set plug at top of Queen 1036' Plugged 280'-380' 35 sacks cement Set plug at base of surface casing. Tagged plug at 273' Mud-laden fluid between plugs. Set 10 sacks plug at surface. Set dry hole marker. Cleaned location. Completed October, 1996 I hereby certify that the information above is true and complete to the best of my knowledge and belief. Agent SIGNATURE . Ruby Parker TYPE OR PRINT NAME (This space for State Use