

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No. N/A
7. Unit Agreement Name N/A
8. Farm or Lease Name O'Brien "R"
9. Well No. 3
10. Field and Pool, or Wildcat Red Lake Ridge San Andres
12. County Chaves

RECEIVED BY
FEB 4 1985
O. C. D.
ARTESIA, OFFICE

SUNDARY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐
Name of Operator
Stevens Operating Corporation
Address of Operator
P. O. Box 2203 Roswell, New Mexico 88201
Location of Well
UNIT LETTER B 660 FEET FROM THE North LINE AND 1980 FEET FROM
THE East LINE, SECTION 28 TOWNSHIP 8-S RANGE 29-E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
3951 GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/>	

16. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-16-85 Move in Desert Rig #1 & Spud @ 6:00 PM, 1-16-85. PTD 380'.
Ran 9 jts 8 5/8 x 24# tbg set & cmnt @ 380' w/225 sxs Class
"C" cmnt w/2% CaCl₂, circ 50 sxs. WOC 18 hrs. Pressure up
1000# for 30 minutes logging no pressure decrease.

1-22-85 PTD 3002', TD @ 4:15 PM, 1-22-85.

1-23-85 Set 100' plug from 2918' to 2818' (40 sxs)
Set 100' plug from 2280' to 2180' (40 sxs)
Set 100' plug from 1786' to 1686' (40 sxs)
Set 100' plug from 1253' to 1153' (80 sxs)
Set 100' plug from 441' to 341' (90 sxs), & Tagged.

1-29-85 Rig up Dowell & pump 3 sxs Class "A" cmnt 2/2% CaCl₂, set
60' Surface Plug.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Production Controller DATE 1-31-85
APPROVED BY [Signature] TITLE Deputy Oil & Gas Inspector DATE 9-13-86
CONDITIONS OF APPROVAL, IF ANY: