Serm 3160-5 Mie Ogn898 Gommis Formeriy 9-331)	sion UNITED	THE INTER	IOR (Other instruct) verse side)	on re- 5. L	Expires August	AND BEBIAL NO
esia, NM 88210	BUREAU OF LAN	D MANAGEMEN	Τ		NM-18611	
SUND	ORY NOTICES ANI orm for proposals to drill or Use "APPLICATION FOR PI	D REPORTS to deepen or plug ERMIT—" for such r	ON WELLS back to a different reservoi.		F INDIAN, ALLOTTEE	OR TRIBE NAME
· · · · · · · · · · · · · · · · · · ·			R EVED		NIT AGREEMENT NA	ME
WELL XX WELL	OTHER					
NAME OF OPERATOR				8. 7	ARM OR LEASE NAM	
Cibola E	Energy Corporation	<u>n</u>	OCT 2.30		Aceite Neg	ra
P. O. BC	ox 1668 Albuque	rque, NM 87	103	. w	FILL NO. 4	
LOCATION OF WELL (Rep	port location clearly and in a	accordance with any	State requirements	10.	FIELD AND POOL, OF	WILDCAT
At surface	i) FtL		ARICON, UTTUR		Wildcat	
330' <del>FEI</del>	& 940' FSL-			11.	SEC., T., B., M., OR B SURVEY OR AREA	LK. AND
					са 12 Т О	S. D 275
4. PERMIT NO.	15. ELEVATIO	NS (Show whether D	. RT. GR. etc.)	1	COUNTY OF PARISH	-
		3880.2			Chaves	NM
	Charle A success to P	au Ta Iadiaasa N	lature of Ninster D		D .	<u> </u>
-		UX TO INGICOTE P	lature of Notice, Repo	•		
	TICE OF INTENTION TO :	ſ		SUBSEQUENT R	EFORT OF:	,
TEST WATER SHUT-OFF			WATER SHUT-OFF		BEPAIRING W	
FRACTUBE TREAT Shoot or acidize	MULTIPLE COM	F1.6.TE	FRACTURE TREATMEN SHOOTING OR ACIDIZ		ALTERING CA ABANDONMEN	
HEPAIR WELL	XX CHANGE PLANS		(Other)		ABANDONMEN	T*
	dalism		(NOTE : Repor	rt results of mu	altiple completion of Report and Log for	on Well
7. DESCRIBE PROPOSED OR C proposed work. If went to this work.) The motor open switches were off for repair Pulling uni following reme 1. Sand ov	ating the jet pum cut. Both Federa t has been moved dial work while was	op was sabota 1 & County of on and tubir vaiting on mo shed off; (f	t details, and give pertinent ions and measured and tru officials were ac ng pulled out of otor repair: ish is packer par	was pulled dvised. M well, pre rt)	d. Wires to Motor has be eparatory to	o kill een moved
7. DESCRIBE PROPOSED OR C proposed work. If nent to this work.). The motor open switches were off for repair Pulling uni following reme 1. Sand ov 2. Cement 3. Cement 4. Perfora 5. Suicide 6. Well to	ating the jet pum cut. Both Federa t has been moved	op was sabota 1 & County of on and tubin waiting on mo hed off; (f 1 to be put 1 led out. below pay. tempted in of by use of sa	t details, and give pertinent ions and measured and tru officials were ac ng pulled out of otor repair: ish is packer par in place; approxi	was pulled dvised. M well, pre rt) imately 3 f water f	d. Wires to Motor has be eparatory to sacks. low.	o kill een moved
7. DESCRIBE PROPOSED OR C proposed work. If nent to this work.)* The motor open switches were off for repair Pulling uni following reme 1. Sand ov 2. Cement 3. Cement 4. Perfora 5. Suicide 6. Well to 7. Well to	ating the jet pum cut. Both Federa t has been moved dial work while w er fish to be was to stabilize fish and fish to be mi tions to be shot squeeze to be at be reperforated be put back on p	on and tubin aiting on mo hed off; (f to be put led out. below pay. tempted in o by use of sa production.	t details, and give pertinent ions and measured and tru officials were ac ng pulled out of otor repair: ish is packer par in place; approxi	was pulled dvised. M well, pre rt) imately 3 f water f	d. Wires to Motor has be eparatory to sacks. low.	o kill een moved
<ul> <li>A DESCRIBE PROPOSED OR C proposed work. If nent to this work.)*</li> <li>The motor open switches were off for repair Pulling uni following reme 1. Sand ov 2. Cement 3. Cement 4. Perfora 5. Suicide 6. Well to 7. Well to</li> <li>Well to</li> <li>Well to</li> <li>Well to</li> </ul>	ating the jet pum cut. Both Federa t has been moved dial work while w er fish to be was to stabilize fish and fish to be mi tions to be shot squeeze to be at be reperforated be put back on p	np was sabota 1 & County of on and tubin vaiting on mo shed off; (f <sup>-1</sup> 1 led out. below pay. ctempted in of by use of sa production.	t details, and give pertinent ions and measured and tru officials were ac ng pulled out of otor repair: ish is packer par in place; approxi order to shut off and jet; one slot	was pulled dvised. M well, pre rt) imately 3 f water f	d. Wires to Motor has be eparatory to sacks. Now. <b>508-6,514</b> <b>DATE</b> Sept	ember 26, 1
7. DESCRIBE PROPOSED OR C proposed work. If nent to this work.)* The motor open switches were off for repair Pulling uni following reme 1. Sand ov 2. Cement 3. Cement 4. Perfora 5. Suicide 6. Well to 7. Well to 7. Well to 8. I hereby certify that th BIGINED HERVEY E (This space for Federal APPROVED BY	ating the jet pum cut. Both Federa t has been moved dial work while w er fish to be was to stabilize fish and fish to be mi tions to be shot squeeze to be at be reperforated be put back on p	rect	t details, and give pertinent ions and measured and tru officials were ac ng pulled out of otor repair: ish is packer par in place; approxi order to shut off and jet; one slot	was pulled dvised. M well, pre rt) imately 3 f water f	d. Wires to Motor has be eparatory to sacks. Now. <b>508-6,514</b> <b>DATE</b> Sept	o kill en moved o the