

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	<input checked="" type="checkbox"/>
LAND OFFICE	<input checked="" type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

CONFIDENTIAL

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole	7. Unit Agreement Name
2. Name of Operator The Superior Oil Company	8. Farm or Lease Name Ivy League Fee
3. Address of Operator 9 Greenway Plaza - Suite 2700 - Houston, TX 77040, C. D.	9. Well No. 1
4. Location of Well UNIT LETTER I 1841 FEET FROM THE S LINE AND 894 FEET FROM THE E LINE, SECTION 9 TOWNSHIP 14S RANGE 24E NMPM.	10. Field and Pool, or Wildcat Wildcat-Montoya
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Chavez

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 2-6-86 RIH w/cmt ret, set @ 5475, sqz perms 5503-5560 w/100x Cl C + 100x "C" Neat (264 cf), dump 155x on top of ret, circ hole w/9.5# MLF, jet cut 5-1/2" csg @ 4990, circ hole w/9.5# MLF.
- 2-7-86 RIH to 5050 & spot 75x Cl C Neat plug, tag plug @ 4915, POH to 4200 & spot 25x Cl C Neat plug, POH to 2975 & spot 25x Cl C Neat plug, POH to 1820 & spot 25x Cl C Neat plug, POH to 1450 & spot 75x Cl C Neat plug, Mike Stubblefield - NMOC, witnessed tagging of plug @ 4915 & was notified of all plugs.
- 2-8/9-86 Tag cmt @ 1305, POH to 565 & spot 25x Cl C Neat plug, POH to 50 & spot 15x Cl C Neat plug to suf.
- 2-10-85 Weld on dry hole marker, clean location, well P&A.

CONFIDENTIAL

Post FD-2
9-19-86
P&A

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Nancy Lewis TITLE MOORE PRODUCING TX & N.M., INC.
AS AGENT FOR THE SUPERIOR OIL COMPANY DATE 3-7-86

APPROVED BY Daniel Moore TITLE Geologist DATE 12/31/86

CONDITIONS OF APPROVAL, IF ANY: