

**UNITED STATES**  
**DEPARTMENT OF THE INTERIOR**  
**BUREAU OF LAND MANAGEMENT**

RECEIVED  
JAN 23 '91  
Q.C.D.  
APPROX. OFFICE

Bulletin Board No. 1004  
Expires Aug. 31, 1985  
LEASE DESIGNATION AND SERIAL

NM-32308

IF INDIAN, ALLOTTEE OR TRIBE

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR  
McKay Oil Corporation

3. ADDRESS OF OPERATOR  
Post Office Box 2014, Roswell, NM 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface  
1485' FWL & 660' FNL

14. PERMIT NO.

15. ELEVATIONS (Show whether OF, RL, OR, etc.)  
4177'

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
L L & E Fed.

9. WELL NO.  
#3

10. FIELD AND FOOT OR FENCE AT  
W. Pecos Slope Abo

11. SEC., T., R., M., OR BLM. AND  
SURVEY OR AREA  
Sec. 12-6S-22E

12. COUNTY OR PARISH  
Chaves

13. STATE  
NM

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO

SUBSEQUENT REPORT OF:

TEST WATER SHUT OFF

PULL OR ALTER CASING

WATER SHUT OFF

REPAIRING WELL

FRAC TREATMENT

MULTIPLE COMPLETION

FRAC TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON\*

SHOOTING OR ACIDIZING

ABANDONMENT\*

REPAIR WELL

CHANGE PLANT

(Other)

Horizontal Drilling

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. Set CIBP @ 2834.5'.
2. Cut window in 4½" casing from 2814' to 2832', 18'.
3. Spot cement plug from 2834' to 2770'. WOC 48 hrs.
4. Drill out cement plug to 2819'.
5. Horizontally drill approximately 300' from existing well bore @ 2848' to the West. Estimated location of the bottom of the hole will be 660' FNL & 1184' FWL, Sec. 12-6S-22E.
6. Drill out cement plug to 2826'. Horizontally drill approximately 300' from existing well bore @ 2848' to the East. Estimated location of the bottom of the hole will be 729' FNL & 1776' FWL, Sec. 12,6S-22e.
7. Run directional surveys to determine location of bottom of holes.
8. Run tubing and production test.
9. Build 40' x 10' x 5' workover pit in same location as old reserve pits.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Operations Manager

DATE 12-11-89

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

SUBJECT TO LIKE  
APPROVAL BY STATE

APPROVED  
PETER W. CHESTER

DEC 14 1989

\*See Instructions on Reverse Side