

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	<input type="checkbox"/>
LAND OFFICE	<input type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-101
Revised 10-1-73

OCT 09 '87

O. C. D.
ARTESIA, OFFICE

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> For <input type="checkbox"/>
5. State Oil & Gas Lease No.	LG 4357

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> GAS <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> P&A	7. Unit Agreement Name Panther Hill Unit
2. Name of Operator Yates Petroleum Corporation	8. Farm or Lease Name Panther Hill Unit
3. Address of Operator 105 South 4th St., Artesia, NM 88210	9. Well No. 1
4. Location of Well UNIT LETTER <u>L 1078</u> 1980 FEET FROM THE South LINE AND 1780 FEET FROM THE West LINE, SECTION 19 TOWNSHIP 8S RANGE 24E NMPM.	10. Field and Pool, or WHcat Pecos Slope Abo
11. Elevation (Show whether DF, RT, GR, etc.) 3675' GR	12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 103.

Propose to plug and abandon well as follows:

- 1) Spot 35 sx cement plug at 3250'. Tag plug at 3100' or higher.
- 2) Spot 35 sx cement plug at 900'. Tag plug at 750' or higher.
- 3) Spot 10 sx cement plug at surface.
- 4) Install regulation abandonment marker.

Use abandonment mud between all plugs.

Notify NMOCD, Artesia, NM, 24 hours before plugging.

Verbal approval to plug as above given by Mr. Les Clements, NMOCD, Artesia, NM, to Ray Stall, YPC, on 10-8-87.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Les A. Clements

TITLE Production Supervisor

DATE 10-8-87

Original Signed By

Les A. Clements

APPROVED BY

TITLE

DATE OCT 20 1987

CONDITIONS OF APPROVAL: Supervisor, District II