
Submit 3 Copies To Appropriate District Office	State of N Energy, Minerals ar	lew Mexico nd Natural Resources			Form C-10 Fixed March 25, 19	
District I 1625 N. French Dr., Hobbs, NM 88240				WELL API NO.	V	
District II OIL CONSERVATION DIVISION				30005-62564	Lagge	
811 South First, Ariesia, Nivi 86210			5. Indicate Type of	_		
<u> </u>			STATE X	FEE L		
District IV				6. State Oil & Gas	Lease No.	
2040 South Pacheco, Santa Fe, NM 87505					T ' A Nome	
SUNDRY NOTICES AND REPORTS ON WELLS				7. Lease Name or U	mit Agreement Nam	ie:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well:				Twin Lakes San Ar	ndres Unit	
Oil Well Gas Well Other Injection				5 NV 11 NV		
2. Name of Operator Concho Oil & Gas Corp.				7. Well No. 8. Pool name or W	Wildoot	
3 Address of Operator				8. Pool name or W Twin Lakes; San An		
110 W. Louisiana Ste 410; Midlan	nd, Tx 79701			Twin Lakes, San Ai	.lures (Assoc)	-
4. Well Location						
Unit Letter_K_: 2300	Feet from the South	line a	nd <u>1700</u> feet from	om the <u>West</u>	_line	
Section 5	Township 9S	Range	29E	NMPM Chaves	County	
	10. Elevation (Show wa	hether DR	, RKB, RT, GR, etc.			
11 Check	Appropriate Box to Ind	licate Na	ture of Notice, I	Report or Other D	ata	
NOTICE OF IN	NTENTION TO:	. 1	SUBS	SÉQUENT REP	ORIOL.	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	7	REMEDIAL WORK		ALTERING CASING	3 🗀
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRI		PLUG AND ABANDONMENT	
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AN CEMENT JOB	1D 🗆		
OTUED.			OTHER:			
OTHER: 12. Describe proposed or compl	eted operations (Clearly st	ate all per	tinent details, and g	give pertinent dates, i	ncluding estimated	date
12. Describe proposed or complete of starting any proposed work or recompilation.	k). SEE RULE 1103. For I	Multiple C	Completions: Attac	h wellbore diagram o	of proposed completi	ion
Concho Oil & Gas Corp. r	ospostfully request a	nnroval	to plug & aban	idon the Twin La	akes San Andre	S
Linit No. 83 according to t	he following procedu	ıre:	to bind or man			
1 Notify NMOCD Arte	sia 24 hrs prior to com	mencem	ent of procedure	e. 081	9202125	
	50-3000' - TAG		•	6770	, 3	
	,0 0000 . 1			(5)	A '2'	
	50_2250'			74	12 Mar 10	
4. Set 100' plug @ 215				$\tilde{\omega}$	ולו ייינרו א	
5. Set 100' plug @ 173	30-1830'. 9 8-1188', WOO 8 lug	B501.	to 950	N R	ECEIVEDIA A)	
6. Set 100' plug @ 100	sourfood	. 00-		\= 00'	D - ARTLON	
/. Circ cmt from 224 t	O Surface.			ું ભૂ	્ર ^{ું} /	
8. Cut off wellhead & i	nstall dry hole marker.			~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	,\$i	
1					90821	
I hereby certify that the informat	ion above is true and comp	lete to the	best of my knowled	e. Property of the state of the		
SIGNATURE	1/With	_TITLE_	Production And		10-18-01	_
()	app C		Telephope Mo. 91	5/683-7443		
(This space for State use)		16.	1.10 13	NO E	DATE_ <i>10-30</i>	111
APPPROVED BY	<u>/0 \ </u>	_TITLE_	The Court of the C	A. Adres -	Auth to set	Dlug
APPPROVED BY Conditions of approval, if any: Whit Stacked out @ 289 at 2877/A.	7' unable to proceed	- All be	silon ferts in	son muses	1-01-01	τσ
•						

TLSAU #83



Original Perf Details: P1: 2850-55, 2857-68, 2873-75, 2878-87, 2890-94 3000 gals 20% acid

P2: 2897, 98, 99, 2900, 2915-24 800 gals 20% acid