

Submit 2 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-005-62595
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	LG-9805
7. Lease Name or Unit Agreement Name	Enron AEY State
8. Well No.	1
9. Pool name or Wildcat	Foor Ranch Wolfcamp

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	RECEIVED OCD ARTESIA
2. Name of Operator YATES PETROLEUM CORPORATION	
3. Address of Operator 105 South 4th St., Artesia, NM 88210	
4. Well Location Unit Letter <u>K</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>West</u> Line Section <u>25</u> Township <u>9S</u> Range <u>26E</u> NMPM <u>Chaves</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3810.6' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Abandon Ordovician and recomple to Wolfcamp <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-17-19-2001 - Moved in and rigged up pulling unit. Nippled down tree and nipped up BOP. TIH and released packer at 5820'. TOOH. TIH with on/off tool and engaged packer with K-valve at 5952'. Could not release packer. Released on/off tool and pulled above perforations. Shut well in for night.

3-20-2001 - TIH and engaged packer at 5952'. Could not release. Released and pulled on/off tool. Rigged up wireline. TIH with CIBP and set CIBP at 5900'. Capped CIBP with 35' of cement. TIH with casing guns and perforated 5538-5551' w/28 .42" holes (2 SPF - Wolf camp). TOOH with casing guns and rigged down wireline. TIH with packer and RBP. Set RBP at 5600'. Pulled packer above perforations and shut well in for night.

3-21-2001 - Acidized perforations 5538-5551' with 1300 gallons of 15% iron control HCL acid and ball sealers. Swabbed. Shut well in.

3-22-2001 - TIH and released RBP and packer. Moved RBP to 5343' and pulled packer above existing perforations 5302-5307' (Wolfcamp). Shut well in.

3-23-2001 - Set packer at 5253' and tested to 1000psi. Acidized perforations 5302-5307'

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

CONTINUED ON NEXT PAGE:

SIGNATURE Rusty Klein TITLE Operations Technician DATE April 30, 2001

TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

SEP 20 2001

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

YATES PETROLEUM CORPORATION
Enron AEY State #1
Section 25-T9S-R26E
Chaves County, New Mexico

SUNDRY NOTICE CONTINUED:


with 3000 gallons of 20% iron control HCL acid and ball sealers. Swabbed. Flow tested. Shut well in.

3-24-26-2001 - Released packer and RBP. TOOH. TIH with packer with on/off tool with 1.81" profile, 1 joint of tubing, seating nipple and tubing. Set packer at 5223'.

Nippled down BOP and nipped up wellhead. Swabbed. Shut well in.

3-27-2001 - Flow tested and swabbed. Shut well in. Released well to production department.

Perforations open: 5302-5307' and 5538-5551' (Wolfcamp)



Rusty Klein
Operations Technician
April 30, 2001