1						
LIGNED Rate	& Collins		Pres. Colli	ns OI1 & Gas	<u>Corp.</u> DATE 10)-6-88
18. I hereby certify	that the information above	is true and complete to the	e best of my knowle	dge and belief.		
,	pumping unit on	ubing and broke of hole and started	l pumping we	11.		
9-30-88	swahhed tubing.					
	balls and broke	formation at 320	0 1bs. Shu	t in well for	8 minutes an	d
9-29-88	Rap 2000' of 2-7	7/8" tubing with ions. Acidized w	packer and a	spotted 2 bbis	s. of acid on HCL. Dropped	
	16 shots 4/10" h 2086, 2090, 2091	holes at 2064, 20 1, 2095, 2109, 21)65,2066,20 23,2125,21	067, 2076, 208 126, 2127.	84, 2085,	
9-28-88	Lagged hold wiht	nent. Cement all t Compensated Neu	itron log.	Perforated cas	sing with	
9–25–88 9–27–88	Ran 2131' of 5 ¹ / ₂ '	vith 200 sks.				
9_25_88	T.D. hole at 213	31'.				
7. Describe Propos work) SEE RUL	E 1 fos.					
OTHER	ed or Completed Operation	a (Clearly state all pertine	nt details, and give	pertinent dates, incl	uding estimated date	of starting any pro
			OTHER	<u>completion</u>		
TEMPORARILY ABAND	<u></u>	CHANGE PLANS	CASING TEST	T AND CEMENT JOB		
PERFORM REMEDIAL		PLUG AND ABANDON		DRILLING OPNS.		TERING CASING Jg and Abandonmen
	NOTICE OF INTENT			SUBSEQU	ENT REPORT O	F:
		oriate Box To Indica	te Nature of N	otice, Report or	Other Data	
		15. Elevation (Show wh 3858 GL	ether DF, RT, GR,	etc.)	12. County Chaves	
THE <u>East</u>	LINE, SECTION					
UNIT LETTER				· .		
Location of Well		FEET FROM THE NOTE	•	//30		
Address of Operation	Box 2443, Roswell	1. NM 88202-2443	3		2	Pool, or Wildcat
	ns Oil & Gas Cor	poration 🗸	<u></u>		Stone Brot	hers State
					8. Farm or Lea	ise Name
JEU TON ODJ	THIS FORM FOR PROPOSALS T USE "APPLICATION FOR P	0 DHILL ON (FORM C-101) FOR	SUCH PROPOSALS.)	<u></u>	7, Unit Agreem	ent Name
	SUNDRY NOT	ICES AND REPORTS	ON WELLS			
DERATOR		•		Q. C. D.	5. State Oil & C LG-5246	jas Lease No.
U.S.G.S.				88' 60 TJO	State X	Foo [
				OCT OK IDO	5a. Indicate Typ	De of Leuse
DISTRIBUT SANTA FE FILE		SANTA FE, N	EW MEXICO	87501		Revised 10-

,

1

ţ