

Submit 3 Copies
to Appropriate
District Office

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Denver DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.	30-006-63132
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	V-2982

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	JUN 18 1997	Angel "AMQ" State
2. Name of Operator United Drilling, Inc.		8. Well No. 1
3. Address of Operator P.O. Box 2488, Roswell NM 88202		9. Pool name or Wildcat Acme- San Andres Southeast
4. Well Location Unit Letter B : 1750 Feet From The South Line and 2310 Feet From The East Section 12 Township 8S Range 27E NMPM Chaves County		
10. Elevation (Show whether DP, RKB, RT, GR, etc.) Ground Level 3942		

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: Attempt completion	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-20-97 Run cement bond log. Cement top at 1600'.
 5-27-97 Perforate 36 holes from 2168' to 2218'.
 5-28-97 Acidized perfs with 4000 gallons of 20% acid, using ball sealers. Balled off perfs with 50 ball sealers.
 Well treated at 890#, I.S.D.P. 340#, 15 minute shut in, 10#, shut well in.
 5-29-97 Swabbed well. Run rods.
 5-30-97 Well put on pump.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Angel Salazar TITLE Vice President DATE 6-2-97
 TYPE OR PRINT NAME Angel Salazar TELEPHONE NO. 623-7730

(This space for State Use)
 APPROVED BY ORIGINAL SIGNED BY TIM W. GUM DISTRICT II SUPERVISOR TITLE _____ DATE JUN 18 1997