

NM OIL CONS. COMMISSION

Drawer DD

Artesia, NM 88210

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-27800

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

MOC Mullis Fed.

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat - 5A

11. SEC. T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 21-T15S-R29E

12. COUNTY OR PARISH 13. STATE

Chaves

NM

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

OIL WELL ☐ GAS WELL ☐ OTHER ☒ Dry Hole - Re-entry

1. NAME OF OPERATOR

McClellan Oil Corporation

3. ADDRESS OF OPERATOR

P. O. Drawer 730, Roswell, NM 88202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

686 FSL & 1995 FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3800 G. L.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☒ Re-entering

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☒

☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12-5 - 12-15-85 Rigged up Cortez Cable Tool. Pulled dry hole marker.

Cleaned out w/8" bit to 1215'. Cleaned out to 2450' w/6" bit.
Could not get past junk in hole at 2450'. Re-plugged well as follows:

50 sx Class C at 2420 ft.

50 sx " " at 1700 ft.

50 sx " " at 1400 ft.

50 sx " " at 350 ft.

10 sx " " at surface.

Installed dry hole marker. Cleaned and leveled location.

Post FD-2
1-24-86
pvt

18. I hereby certify that the foregoing is true and correct.

SIGNED [Signature] TITLE Operations Manager

DATE 1-3-86

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____
CONDITIONS OF APPROVAL, IF ANY:

APPROVED
DATE
PETER W. CHESTER

JUL 31 1987

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA

*See Instructions on Reverse Side