

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator M. C. Gandy	8. Farm or Lease Name State #2-A - Max Pray
3. Address of Operator P O. Box 827, Tatum, New Mexico	9. Well No. #2
4. Location of Well UNIT LETTER <u>AN</u> 1980 FEET FROM THE <u>W</u> LINE AND 660' FEET FROM THE <u>S</u> LINE, SECTION <u>30</u> TOWNSHIP <u>15S</u> RANGE <u>29E</u> NMPM.	10. Field and Pool, or Wildcat <u>Round Tank Long Andrus</u>
15. Elevation (Show whether DF, RT, GR, etc.) 3072 TD	12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Load hole with mud  
20 Sack Plug TD  
20 Sack Plug @ Stub of 4 1/2  
20 Sack Plug @ 1500'  
20 Sack Plug @ Base of Surface  
Surface Marker

Approximate starting date: April 6, 1966

RECEIVED

1966  
APR 7  
1966

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED By: <u>Jim Conine, Inc.</u>	TITLE <u>Agent</u>	DATE <u>4-5-66</u>
APPROVED BY <u>W. A. Gussessett</u>	TITLE <u>W. A. Gussessett</u>	DATE <u>APR 7 1966</u>
CONDITIONS OF APPROVAL, IF ANY:		