

SUBMIT IN TRIPLICATE\*  
(Other instructions on reverse side)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

5. LEASE DESIGNATION AND SERIAL NO

NM-54400

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Shell 15 Fed. Comm.

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 15-T15S-R29E

12. COUNTY OR PARISH 13. STATE

Chaves

NM

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐  
2. NAME OF OPERATOR  
McClellan Oil Corporation  
3. ADDRESS OF OPERATOR  
P.O. Drawer 730, Roswell, N.M. 88202  
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)  
At surface  
660 FNL & 660 FWL

CONFIDENTIAL INFORMATION  
RECEIVED

JAN 26 '88

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3907 G.L.

O. C. D.

ARTESIA, OFFICE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETION

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON\*

SHOOTING OR ACIDIZING

ABANDONMENT\*

REPAIR WELL

CHANGE PLANS

(Other)

(Other)

Plug Back

X

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Present perfs 8370 - 8428

Propose to plug present perfs, shoot off 5 1/2" casing at 6900 ft and pull casing, then set cement plugs in the 5 1/2" casing stub, at 5950 ft across the Abo top and at 4100 ft in and out of the 8 5/8" casing shoe. Then, propose to perforate and acidize the Queen formation in the 8 5/8" casing.

① CIBP at 8300' + 35' cmt. cap.

② 100' minimum cmt. plug 6950'-6850' tag plug

③ 100' minimum cmt. plug 4123-4023. tag plug.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Operations Manager

DATE

12/8/87

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED  
DATE  
PETER W. CHESTER

DEC 9 1987

\*See Instructions on Reverse Side