

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRI
(Other instruction on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR JACK L. MCCLELLAN		8. FARM OR LEASE NAME LISA FEDERAL	
3. ADDRESS OF OPERATOR Box 343, Roswell, New Mexico 33201		9. WELL NO. 1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1930' FSL & 1980' FWL		10. FIELD AND POOL, OR WILDCAT WILDCAT	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA SEC. 13-15S-29E	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3926' G. L.		12. COUNTY OR PARISH CHAVES	
		13. STATE NEW MEXICO	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☒
SHOOTING OR ACIDIZING ☐
(Other) ☐

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

MAY 14, 1963: PERFORATED 1 SHOT PER FOOT FOR 16 SHOTS FROM 3342' - 3431'.

MAY 15, 1968: RAN TUBING 3500' WITH PACKER AND ACIDIZED WELL WITH 5000 GALS. 15% ACID.

MAY 27, 1963: FRACED WITH 40,000 GALS. 3342' - 3431'. SET A WIRE LINE BRIDGE PLUG AT 3322'. PERFORATED 16 SHOTS 3286 - 98'. ATTEMPTED TO BREAK THIS ZONE DOWN WITH 1000 GALS. ACID. RE-PERFORATED 16 SHOTS 3288 - 3300' WITH CASING GUN. AFTER SEVERAL HOURS FORMATION BROKE AND FRACED THIS ZONE WITH 20,000 GALS. TREATED WATER, 1# SAND PER GAL.

RECEIVED

MAY 5 1968

U. S. G. S.
ARTESIA OFFICE

RECEIVED

MAY 29 1968

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the log is true and correct

SIGNED J. L. McClellan TITLE OPERATOR DATE MAY 28, 1968

(This space for Federal or State office use)

TITLE _____ DATE _____

APPROVED BY _____

MAY 29 1968

R. L. BLENMAN
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963—O-685229

GPO 8 37-499

8 87-6 51