

N. M. O. C. C. COPY

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-0199070-B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Amco-Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

31 14S 30-E

12. COUNTY OR PARISH 13. STATE

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS

Use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.

☒ WELL ☐ OTHER

MAJOR

Alport Oil Corporation

CREATOR

1 First National Bank Bldg Dallas, Texas 75202

WELL (Report location clearly and in accordance with any State requirements.
See 17 below.)

1980' FSL & 660 FWL Sec. 31

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

WATER SHUT-OFF

PULL OR ALTER CASING

REPAIR

MULTIPLE COMPLETE

REPAIRS

ABANDON*

WELL

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

Setting Casing

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to the work.)

Completed 1:50 P. M. 7-31-69

115' 8 5/8" 20# casing. Cemented w/175 sacks 2% Caci-cement
circulated

2. C. 18 hours - Tested 600#s 30 minutes. Tested O. K.

RECEIVED
AUG-5 1969
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

that the foregoing is true and correct

TITLE President

DATE 8/4/69

Federal or State office use)

TITLE

DATE

OF APPROVAL, IF ANY
District Engineer

*See Instructions on Reverse Side