Form 3160-5 (November 1994)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED

14.101.	<b>UII</b>	Cons	Division No. 1004-0135
1625	NI I	r [	Divisit Fires July 31, 1996
1023	14.	rrenc	O Re Serial No

11. S W Wall, Suite 1900, Midland, TX 79701   30 - 005 - 20309   10. Field and Pool, or Exploratory Area Double L Queen   10. Field and Pool, or Exploratory Area Double L Queen   11. Courty or Parish, State Chaves   12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA   TYPE OF SUBMISSION   TYPE OF ACTION   Water Shut-Off   Activation   Activation   Production (Start/Resume)   Water Shut-Off   Wat	Do not use to abandoned w	RY NOTICES AND REPORT This form for proposals to well. Use Form 3160-3 (APD)  RIPLICATE - Other instruction	ide	6. If Indian, Allottee or Tribe Name  7. If Unit or CA/Agreement, Name and/or No.  8910160560  8. Well Name and No.  Double L Queen No 1  9. API Well No.  30-005-20309  10. Field and Pool, or Exploratory Area  Double L Queen  11. County or Parish, State				
TYPE OF SUBMISSION    Acidize								
Notice of Intent   Asidize	12. CHECK A	PPROPRIATE BOX(ES) TO	INDICATE NATUR	E OF NOTICE, RE	PORT, OR OTHER DATA			
Notice of Intent	TYPE OF SUBMISSION		TYPE OF ACTION					
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations measured and true vertical depths of all pertinent markers and subsets. Attach the Bond under which the work will be performed or provide the Bond No. on fill with BIAMBIA. Required subsequent reports whall be filled once the string has been completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160 phall be filled once testing has been completed. Final Abandonment Notices shall be filled only after all requirements, including reclamation, have been completed, and the operations determined that the site is ready for final inspection.)  Intent to P&A this SI WIW, will notify OCD 24 hrs prior to start operations  MIRU, POOH w/rods, NU BOP, POOH w/tbg  (5-1/2" csg @ 2024' w/150 sx Perfs 1980'94')  Set CIBP @ 1930' w/35' cmt on top  RIH, circ well w/9.8# mud  POOH to 1300', spot 100' cmt plug  POOH to 439', spot 100' cmt plug (8-5/8" @ 389' w/50 sx), WOC & tag  POOH to 300', spot 100' cmt plug (8-5/8" @ 389' w/50 sx), WOC & tag  POOH to 300', spot 100' cmt plug (8-5/8" @ 389' w/50 sx), WOC & tag  POOH to 300', spot 100' cmt plug (8-5/8" @ 389' w/50 sx), WOC & tag  POOH to 300', spot 100' cmt plug (8-5/8" @ 389' w/50 sx), WOC & tag  POOH to 300', spot 100' cmt plug (8-5/8" @ 389' w/50 sx), WOC & tag  POOH to 300', spot 100' cmt plug (8-5/8" @ 389' w/50 sx), WOC & tag  POOH to 300', spot 100' cmt plug (8-5/8" @ 389' w/50 sx), WOC & tag  POOH to 439', spot 100' cmt plug (8-5/8" @ 389' w/50 sx), WOC & tag  POOH to 300', spot 100' cmt plug (8-5/8" @ 389' w/50 sx), WOC & tag  POOH to 439', spot 100' cmt plug (8-5/8" @ 389' w/50 sx), WOC & tag  POOH to 439', spot 100' cmt plug (8-5/8" @ 389' w/50 sx), WOC & tag  POOH to 439', spot 100' cmt plug (8-5/8" @ 389' w/50 sx), WOC & tag  POOH to 439', spot 100' cmt plug (8-5/8" @ 389' w/50 sx), WOC & tag  POOH to 430', spot 100' cmt plug (8-5/8" @ 389' w/50 sx), WOC & tag  POOH to 430', spot 100' cmt plug (8-	☐ Subsequent Report	☐ Alter Casing ☐ Casing Repair ☐ Change Plans	Fracture Treat  New Construction  Plug and Abandon	Recomplete Temporarily Aband	☐ Well Integrity ☐ Other A D. F.			
Name (Printed/Typed)  Bonnie Husband  Signature  Date	If the proposal is to deepen dired Attach the Bond under which the following completion of the investing has been completed. Find determined that the site is ready Intent to P&A this SI WIW MIRU, POOH w/rods, NU (5-1/2" csg @ 2024' w/15' Set CIBP @ 1930' w/35' or RIH, circ well w/9.8# mud POOH to 1300', spot 100' POOH to 439', spot 100' POOH to 20', circ cmt to set involved the set of the site of the set	ectionally or recomplete horizontally, he work will be performed or provide to level operations. If the operation results Abandonment Notices shall be filled for final inspection.)  If will notify OCD 24 hrs price of the property of the p	give subsurface locations methe Bond No. on file with BI alls in a multiple completion of only after all requirements, or to start operations	astired and true vertical of M/BIA. Required subset or recompletion in a new including reclamation, has the court of the c	depths of all pertinent markers and runes.  quent reports shall be filed frithing to, days interval, a Form 31607 shall be filed once ave been completed, and the operation has  The pure o 439 — Fill Amount  The Pure  The Pure			
	Name (Printed/Typed) Bonnie Husband	ing is true and correct	Produc	ion Analyst				
		Shistand	10/25/2	000				

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Office

भारत असी

Approved by

THE ENGLISH AND PLACE

1966 FIX 250

202 STAN 25 20 2)