

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Co. Division
1625 N. French Dr.
Hobbs, NM 88240

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.
NM17114

6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☐ Gas Well ☒ Other

2. Name of Operator

Saga Petroleum LLC

3. Address and Telephone No.

415 W. Wall, Suite 1900, Midland, TX 79701

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1650' FNL & 990' FWL Unit Letter E
Sec. 18, T-15-S, R-30-E

7. If Unit or CA, Agreement Designation

8910160560
Double L Queen Unit Tract #1

8. Well Name and No.

Double L Queen Tract 1 #7

9. API Well No.

30-005-20385

10. Field and Pool, or Exploratory Area

Double L Queen

11. County or Parish, State

Chaves, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent
☐ Subsequent Report
☒ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

3-26-01 Set 5-1/2" CIBP @ 1930', cap w/ 35' cmt. w/ dump bailer.
3-26-01 Mix mud & circ. hole.
3-26-01 Perf 4 holes @ 1300', sqz 35 sx cmt., tag @ 1198'. Pkr. set @ 1050'.
3-26-01 Perf 4 holes @ 358', set pkr. @ 60', squeeze 35 sx cmt.
3-27-01 Tag plug @ 230'.
3-27-01 Perf @ 50', circ. 10 sx cmt. to Surface out of 8-5/8" csg, leave 5-1/2" full of cmt.
3-27-01 Install dry hole marker.

Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

14. I hereby certify that the foregoing is true and correct

Signed

Title

Agent

Date

3-29-01

(This space for Federal or State office use)

(ORIG. SGD.) DAVID R. GLASS

Title

PETROLEUM ENGINEER

Date

APR 04 2001

Approved by
Conditions of approval, if any:

RECEIVED
APR 03 2001
BLM
ROSWELL, NM

