	N.M.O.C.D. CO	PY	じ. フィ
Form 9-331 (May 1963)		Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO. NM-9402 6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
(Do not use this form for f Use "AP	OTICES AND REPORTS ON proposals to drill or to deepen or plug back PLICATION FOR PERMIT—" for such prop	WELLS to a different reservoir.	7. UNIT AGREEMENT NAME
1. OIL GAS WELL CAS WELL OTH 2. NAME OF OPERATOR	ER	AUG 1 7 1979	8. FARM OR LEASE NAME
Yates Petroleum Corporation     3. ADDRESS OF OPERATOR         D. C. C.			Octonwood KI Fed. Com 9. WELL NO.
207 South 4th Street-Artesia, NM 88210 ARTESIA, DFFID: 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface			10. FIELD AND FOOL, OR WILDCAT Undesignated
1980' FSL & 1980' FEL of Section 17-165-25E			11. SEC., T., B., M., OF BLK. AND SUBVEY OF ABEA Sec. 17-16S-25E Unit J NMPM
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, B 3542 GR	r, gr, etc.)	12. COUNTY OF PARISH 13. STATE   Eddy NM
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF:			
<pre>proposed work. If wen is nent to this work.)* WIH w/RBP, Baker packer at 7119'. shot at each poi 07, 14, 19, 27, 17 and 19'. Trea sealers. Swabbe TD 7400'; PBTD RBP at 7347' and of hole. WIH w/ holes (2 spf). Swabbed well dry ball sealers. Sw TD 7400'; PBTD ( packer. RIH w/ at 6948'. WIH w/ holes (4 spf). treated perfora cleaned up and</pre>	PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS Units The subsurface location TED OPERATIONS (Clearly starts in perminent directionally drilled, give subsurface location Lok-Set packer on 2- Perforated w/Casing int) as follows: 713 31, 35, 37, 39,41, 43 ated perforations w/20 ed well w/ a show of a MO96'. Loaded hole and moved up hole to 700 /casing gun on Wirelit WIH w/Baker packer of y. Treated w/ 1000 g wabbed w/ a show of g 5948' - Loaded hole, tubing and latched on w/casing gun on Wirelit WIH w/packer on 2-7/ tions w/1000 gallons flowed 250 <sup>‡</sup> on 20/64" going is true and correct Multiple and correct Multip and correct Multiple and correct Multiple a	Completion or Recompl defails, and give pertinent dates, ns and measured and true vertice -7/8" tubing. Se gun 7137-7319' w 7, 39, 43, 57, 71 3, 45, 47, 49, 51 DOO gallons 15% D gas. TSTM. nd unseated packet D6'. Pulled tubin ne and perforated n 2-7/8" tubing, allons 15% DS-30 as TSTM. unseated packer. to RBP and pulled ine and perforated 8" tubing, set packet 15% DS-30 acid an	of multiple completion on Well letion Report and Log form.) including estimated date of starting any al depths for all markers and zones perti- et RBP at 7347 and 2/29 .50" holes (1 4, 73, 83, 97, 7203, 4, 7301, 03, 13, 15, 0S-30 acid w/ball er, latched on to ing and packer out 4 7045-51' w/12 .50" set packer at 6992'. acid & Nitrogen w/ POH w/tubing and ed up hole and set ed 6868-74' w/24 .50" acker at 6826' and nd Nitrogen. Well
(This space for Federal or S APPROVED BY 100 CONDITIONS OF APPROVA	gt flews , T TITLE	NO DISTRICT ENGINEER	DATE <u>AUG 1 6 1979</u>

.

\*See Instructions on Reverse Side

.