

Submit 3 Copies To Appropriate District Office
 District I
 1625 N. French Dr., Hobbs, NM 87240
 District II
 811 South First, Artesia, NM 87210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised March 25, 1999

OIL CONSERVATION DIVISION
 2040 South Pacheco
 Santa Fe, NM 87505

else

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015- 30693
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator OXY USA Inc. 16696		6. State Oil & Gas Lease No. LG584
3. Address of Operator P.O. BOX 50250 MIDLAND, TX 79710-0250		7. Lease Name or Unit Agreement Name: Oxy Sosa State
4. Well Location Unit Letter <u>K</u> : <u>1780</u> feet from the <u>South</u> line and <u>1980</u> feet from the <u>West</u> line Section <u>12</u> Township <u>17S</u> Range <u>27E</u> NMPM EDDY County		8. Well No. 1
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3461'		9. Pool name or Wildcat Undsg. Crow Flats Morrow

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> OTHER: <input type="checkbox"/>		SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <u>Complete & SI</u> <input checked="" type="checkbox"/>	
---	--	---	--

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

See other side



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *David Stewart* TITLE REGULATORY ANALYST DATE 1/14/00

Type or print name DAVID STEWART Telephone No. 915-685-5717
 (This space for State use)

APPROVED BY *Miss Sheffield* TITLE Field Rep. # DATE 2/4/2000
 Conditions of approval, if any:

ATTACHMENT C-103
OXY USA INC.
OXY SOSA STATE #1
SEC 12 T17S R27E
EDDY COUNTY, NM

MIRU PU 8/24/99, RIH W/ CBL, TOC @ 7833', CHC. RIH W/ TCP GUNS, BAKER LS PKR (9084') & 2-3/8" TBG. DROP BAR & PERF ATOKA W/ 4SPF @ 9136-9145', TOTAL 40 HOLES. GAS TO SURFACE IN 9min, NO FLUID, 4' FLARE. WATCH FOR 1hr FLARE DECREASED TO 2', NO FLUID. SWAB 3BW IN 1hr, SWABBED DRY W/ 2' FLARE. WAIT 1hr, RIH W/ SWAB, NO FLUID ENTRY. SITP-2100#, OPEN WELL TO PIT ON 10/64 CHK, BLED DOWN TO 200# IN 3hrs. SWAB 4BO, 1BW IN 1hr, SWABBED DRY, W/ 0# W/ 4' FLARE. MAKE 1 SWAB RUN/HR FOR 7hrs W/ NO FLUID ENTRY. RU WL, RIH & SHIFT GUNS OFF, CHASE TO TD, GUNS @ 9582'. ACIDIZE W/ 2000gal 7½% HCl ACID W/ 142000 MSCF N2 & 400gal METHANOL, SIP-5334#. OPEN WELL TO PIT ON 10/64 CHK, PRESSURE DROPPED TO 1325# IN 3hrs. OPEN TO FULL CHK, PRESSURE DROPPED TO 30# IN 3½hrs, REC 39BW IN 8hrs. SITP-2550#, OPEN WELL TO PIT ON 12/64 CHK, BLED TO 500# IN 1hr. CHK TO 8/64, PRESSURE BUILT TO 550#, FLWD WELL TO PIT ON 8/64 CHK FOR 11hrs FOR 1½BO, 0BW, FFTP-550#, EST 190MCFD. SITP-2650#, OPEN WELL TO PIT, BLED TO 25# IN 2hrs FOR 2BO. SWAB 2BO, 3BW IN 6hrs, SWABBED DRY IN 1hr, W/ 100-200' FLUID ENTRY W/ ROLLING 4' FLARE. RDPU 8/30/99, SIW, PENDING ENGR EVAL.