

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN DUPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. New Mexico USA 0559078	
2. NAME OF OPERATOR Humble Oil & Refining Co.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR Box 1600, Midland, Texas		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit K 1837 FS&WL		8. FARM OR LEASE NAME Humble Yates Federal	
14. PERMIT NO.		9. WELL NO. 1	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) to be supplied later 5406 GR.		10. FIELD AND POOL, OR WILDCAT Wildcat	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA S26, T15S, R18E	
		12. COUNTY OR PARISH Chaves	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>
FRACTURE TREAT	<input checked="" type="checkbox"/>	FRACTURE TREATMENT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	(Other)	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		
PULL OR ALTER CASING	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
MULTIPLE COMPLETION	<input checked="" type="checkbox"/>	ALTERING CASING	<input checked="" type="checkbox"/>
ABANDON*	<input type="checkbox"/>	ABANDONMENT*	<input checked="" type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>		

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Drld to 5392' TD on 5-20-67. Well dry. Set plug #1 fr 5000-5300 w/60 sx portland cmt w/12.5# Gilsonite & 1/2# floseal & 2% ca chl per sack. Set plug #2 fr 4200-4300 w/43 sx ditto. Set plug #3 fr 2730-2830 w/14 sx ditto. Plug placed in 7" csg using HOWCO OC pkr set @ 2780' w/50' cmt above & 50' below pkr. Cut off 7" csg @2360' and pulled and recovered same. Left 420' 7" csg in hole. Set plug #4 fr 1500-1600' w/42 sx ditto. Set plug #5 fr 1020-1120' w/72 sx ditto using a DC pkr w/1050' w/36 sx cmt above & 36 sx below pkr. Set plug #6 fr 300-306' w/5 sx ditto inside 8-5/8" csg. Placed swedge & valve on top. Installed dry hole marker. Will notify your office when location is clean and ready for final inspection.

RECEIVED

JAN 30 1969

D. C. C.
ARTESIA, OFFICERECEIVED
MAY 26 1967
U.S. GEOLOGICAL SURVEY
NEW MEXICO
DATE 5-25-67

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Agent

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: