

|                        |   |
|------------------------|---|
| NO. OF COPIES RECEIVED | 6 |
| DISTRIBUTION           |   |
| SANTA FE               | / |
| FILE                   | / |
| U.S.G.S.               |   |
| LAND OFFICE            |   |
| OPERATOR               | 4 |

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

|  |
|--|
| 5a. Indicate Type of Lease   |
| State <input checked="" type="checkbox"/> Fee <input type="checkbox"/> |

5. State Oil & Gas Lease No.  
OG 6058

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

|   |  |
|---|--|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>                            | 7. Unit Agreement Name<br>N/A  |
| 2. Name of Operator<br>SOUTHWEST PRODUCTION CORPORATION   | 8. Farm or Lease Name<br>CLEMENTS BUFFALO VALLEY <i>com</i>          |
| 3. Address of Operator<br>BOX 936 - ROSWELL, NEW MEXICO 88201   | 9. Well No.<br>1   |
| 4. Location of Well<br>UNIT LETTER D 990' FEET FROM THE NORTH LINE AND 990' FEET FROM THE WEST LINE, SECTION 1 TOWNSHIP 15S RANGE 27E NMPM. | 10. Field and Pool, or Wildcat<br>Undesignated <i>Buffalo Valley</i> |
| 15. Elevation (Show whether DF, RT, GR, etc.)<br>3521' GL   | 12. County<br>CHAVES   |

|  |   |
|--|---|
| 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data |   |
| NOTICE OF INTENTION TO:  | SUBSEQUENT REPORT OF:                               |
| PERFORM REMEDIAL WORK <input type="checkbox"/>                               | REMEDIAL WORK <input type="checkbox"/>              |
| TEMPORARILY ABANDON <input type="checkbox"/>                                 | COMMENCE DRILLING OPNS. <input type="checkbox"/>    |
| PULL OR ALTER CASING <input type="checkbox"/>                                | CASING TEST AND CEMENT JOB <input type="checkbox"/> |
| OTHER WHIPSTOCK <input checked="" type="checkbox"/>                          | OTHER <input type="checkbox"/>                      |
| PLUG AND ABANDON <input type="checkbox"/>                                    | ALTERING CASING <input type="checkbox"/>            |
| CHANGE PLANS <input type="checkbox"/>  | PLUG AND ABANDONMENT <input type="checkbox"/>       |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

11/13/67 While drilling at 7456' hole started heaving and pipe got stuck. While blowing hole with air, had down hole fire. Pulled out of hole and recovered 6½ drill collars. Could not recover remaining 15½ drill collars.

11/18/67 Prep to set whipstock at 6660' to drill around drill collars left in hole at 6920' to 7420'.

NOTE: Copy of this report is being set to offset operators.

|  |                           |                        |
|--|---------------------------|------------------------|
| 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. |                           |                        |
| SIGNED <i>H. Lee Harvard</i><br>H. LEE HARVARD   | TITLE EXPLORATION MANAGER | DATE 12/1/67           |
| APPROVED BY <i>W. A. Bessett</i>   | TITLE <i>INSPECTOR</i>    | DATE <i>DEC 1 1967</i> |
| CONDITIONS OF APPROVAL, IF ANY:  |                           |                        |