12. COUNTY OR PARISH 13. STATE

REPAIRING WELL

ALTERING CASING

CHAVES

SUBSEQUENT REPORT OF:

		N. M. O. C. C. COPY	Carry to
	m 9-331 ly 1963)	L TED STATES SUBMIT IN TR. CATE DEPARTMENT OF THE INTERIOR verse side)	5. LEASE DESIGNATION AND SERIAL NO.
		GEOLOGICAL SURVEY	NM 0284972
	(Do nat	SUNDRY NOTICES AND REPORTS ON WELLS use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
1.			7. UNIT AGREEMENT NAME
	WELL	WELL OTHER DRY HOLE	
2.	NAME OF OPE	MCCLELLAN 4	8. FARM OR LEASE NAME YATES "BB" FEDERAL
3.	ADDRESS OF		9. WELL NO.
	P. O.	Box 848, Roswell, New Mexico, 88201	2
4.	LOCATION OF See also spac At surface	well. (Report location clearly and in accordance with any State requirements.* ce 17 below.)	10. FIELD AND POOL, OR WILDCAT WILDCAT
	330' F	NL & 1650' FWL	11. SEC., T., R., M., OF BLK. AND SURVEY OF AREA SEC. 27-T15S-R29E

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

NOTICE OF INTENTION TO:

PULL OR ALTER CASING

MULTIPLE COMPLETE

3840' G. L.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

WATER SHUT-OFF

FRACTURE TREATMENT SHOOTING OR ACIDIZING

14. PERMIT NO.

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

16.

REPAIR WELL	CHANGE PLANS	(Other) (Note: Report results of multiple completion on Well	_
(Other)		Completion or Recompletion Report and Log form.)	
17. DESCRIBE PROPOSED (proposed work. I nent to this work.)	If well is directionally drilled, give	state all pertinent details, and give pertinent dates, including estimated date of starting subsurface locations and measured and true vertical depths for all markers and zones	ag any i perti-

ON MAY 31, 1970, Mr. James Knauf gave verbal permission for the plugging AND ABANDONING OF THIS TEST AS FOLLOWS:

SET 100' (30 SACK) CEMENT PLUG FROM 1825 TO 1725' (T. D.) SET 100' (30 SACK) CEMENT PLUG FROM 935 TO 835'. SET 100' (30 SACK) CEMENT PLUG FROM 370 TO 270'. (10 SACK) CEMENT PLUG FROM 30 TO SURFACE.

PLACE HEAVY MUD BETWEEN PLUGS, INSTALL DRY HOLE MARKER, CLEAN LOCATION.

> RECEIVED AUG- 4 1970 N. S. GEOLOGICAL SHIPMEN ARTESIA, NEW MEXICO

18. I hereby certag that the see strue and correct		466-0		_
SIGNED Jan & M. C. Clalla	TITLE	OPERATOR	DATE 7/31/70	_
(This space for Pederal or State C	TITLE		DATE	_

*See Instructions on Reverse Side