

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TR. CATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.5. LEASE DESIGNATION AND SERIAL NO.
NM-0282501-A

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
2. NAME OF OPERATOR United States Smelting Refining and Mining Company ✓	7. UNIT AGREEMENT NAME
3. ADDRESS OF OPERATOR 19th Floor University Club Bldg., 136 East South Temple Salt Lake City, Utah 84111	8. FARM OR LEASE NAME Federal 1360
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 2310' FWL & 2310' FWL Sec. 26, T-15-S, R-29-E	9. WELL NO. 1
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3905' GR
	10. FIELD AND POOL, OR WILDCAT Sulimar
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 26, T-15-S, R-29-E
	12. COUNTY OR PARISH Chaves
	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☒CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Reached T.D. of 2113', 10-7-70 Ran logs, no Commercial Show indicated.
2. Place 28 sacks cement plug 1850' to 1950'.
3. Place 28 sacks cement plug 1035' to 1135'.
4. Place 28 sacks cement plug 365' to 465' in bottom of surface casing.
5. Place 10 sacks cement plug in top of surface casing.
6. Install 6' dry hole barrier per USGS requirements.

All intervals between cement plugs to be laden with heavy mud.
Verbal plugging instructions as outlined above given by USGS.

RECEIVED

RECEIVED

OCT 10 1970

NOV 2 1970

J. L. ARTESIA OFFICE

18. I hereby certify that the foregoing is true and correct

SIGNED

T. B. Garber

TITLE

Manager of Oil Operations

DATE

10-7-70

(This space for Federal or State office use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

APPROVED

DATE RECEIVED