Do not	BUREAU OF LAND MAN JNDRY NOTICES AND REF use this form for proposals is	E INTERIOR JAGEMENT P ORTS ON WELLS To drill or to re-enter an	1301 V& Lease Serial No. 1004-0135 NM-028250 V& Nue 6. If Indian, Allofte 2010 Be Name
abandor	ned well. Use Form 3160-3 (Al IN TRIPLICATE - Other inst	PD) for such proposals.	7. If Unit or CA/Agreement, Name and/or No.
990' FSL & 99 Sectin 26 Tl	s, Inc. <u>B</u> Roswell, NM 88202 ge, Sec T., R., M., or Survey Descripti D' FWL 5S-R29E	3b. Phone No. (include bitacept 505/622-3770 ART on)	ESIA 10. Field and Pool, or Exploratory Area Sulimar Queen 11. County or Parish State
TYPE OF SUBMISSIO		TYPE OF A	
Notice of Intent	 Acidize Alter Casing Casing Repair Change Plans 	Image: Spectrum of the system Image: Spectrum of the	oduction (Start/Resume) Image: Water Shut-Off iclamation Image: Well Integrity icomplete Image: Other imporarily Abandon Image: Water Shut-Off
Final Abandonment No Describe Proposed or Co	mpleted Operation (clearly state all pe	rtinent details, including estimated star	ting date of any proposed work and approximate duration thereof.

If the proposed of complete operation creatly state an period and stating data and approximate duation direction. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Read & Stevens proposes to plug and abandon the subject well by setting a CIBP at 1,870' over the existing perforations of 1,890'-1,906', and capping with 35' of cement. The 5 $\frac{1}{2}$ " casing will then be cut and pulled from the free point estimated at 1,222' from a calculated top of cement. A 100' cement plug will be set at the 5 $\frac{1}{2}$ " casing stub. A 100' cement plug will be set at the shoe of the 8 5/8" casing at 292', and a 50' surface plug will be set after cutting off the wellhead.

	the record . Pitte
14 Thereby certify that the foregoing is true and correct Name (Printed/Typed)	becerved be rea
John C. Maxey, Jr.	Title Operations Manager
Signature Milching	Date 4-10-02
APPROX E DIS SPAC	E FOR FEDERAL OR STATE OFFICE USE
Approved by (ORIG. SGD.) DAVID R. GLAS	
Conditions of approval, if applie attached OG2 proval of this n certify that the applicant holds legal or equitable title to those n which would entitle the applicant to conduct operations thereon.	notice does not warrant or rights in the subject lease
	nake it a crime for any person knowingly and willfully to make to any department or agency of the United ons as to any matter within its jurisdiction.