NO. 04 COPIES RECEIVED	
DISTRIBUTION	Form C-103 Supersedes (IId
	C-102 and C-103 Effective 1-1-65
U.S.G.S. JUN 9 1976	5a. Indicate Type of Leas
	5. Stele Off & Gas Lease No. K-5999
SUNDRY NOTICES AND REPORTED IN MERCENE (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN C' PLUG PACA TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) / DE SUCH PROPOSALS.)	AIIIIII . South
	7. Unit Agreement Name
Vates Petroleum Corporation V	8. Farm or Leane Marie
3. Ad iress of Operator	Dunken Dome Unit
207 South 4th Street-Artesia, NM 88210	1
UNIT LETTER K 1700 FEET FROM THE West 1980	10. Field of the Waltant Wildcat
THE South . LINE, SECTION 7 TOWNSHIP 175 RANGE NMPM.	
16. 15. Elevation (Show whether DF, RT, GP, etc.) 16. 5392' GR	12. County Chaves
Check Appropriate Box To Indicate Nature of Notice, Report or Oth NOTICE OF INTENTION TO:	er Data
SUBSEQUENT	REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	SUTERING :
PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT 200	PLUS AND ADAL DONMENT L
OTHER Perf, treat, p	lug back
OTHER	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.	ar proposition
TD 5826'; PBTD 4789' by wireline. RIH w/2-3/8" tubing w/tubing Conveyed Gun and Guiberson Uni-VI packer set at 4486'. Perforated w/40 .34" (4 JSPF) 4544-4554'. Acidized w/1000 gallons of 15% DS-30 acid w/50 ball sealers. Opened well and well flowed for 40" and died. Unable to swab well back. Rigged up Halliburton. WIH w/RTTS packer, set packer at 4390'. Squeezed perforations 4544-4554' w/100 saks of Class C w/3# salt/sx of cement. Squeezed to 2100#, reversed out tubing, pulled 5 stands, reset packer and repressured to 1500#. SI. RIH, drilled out cement and cleaned hole to 4796' after WOC. POH, perforated Penn Sand at 4565-67 w/8 .34" holes. RIH w/tubing and packer, set packer at 4548' and swabbed well. No show of gas or oil. Broke down perfs. w/200 gallons DS-30. Swabbed well, recovered small show of gas and salt water. Swabbed well. 3000' of fluid in hole, unable to swab down. Moved in workover unit and set 5½" Cast Iron Bridge Plug at 4400'. Dumped 16' of cement on top & Perforated at 3400' w/4 1/2" holes for block squeeze. Set retainer at 3376' & sqz w/100 sx of Class C w/6# salt/sx and 1/2 of 1% CFR-2. Ran cmt Bond log-good bond at 3140'-probable top of cmt at 2800'. WIH & perf 3332-3346'w/2 JSPF.50" hole: Ran 2-3/8" tubing w/Guiberson Uni-VI pkr, set pkr at 3320'. SI- Op, no show of oil 18.1 hereby centify that the information above is trub and complete to the co	
SIGNED Arubia tomburan TITLE Geol. Secty	6-8-76
APPROVED BY A A CONDITIONS OF APPROVAL, IF ANY:	JUN 9 1976

TD 5826'; PBTD 3373'. Acidized perforations 3332-3346' w/500 gallons of 15 % DS-30 acid. Well went on vacuum in 1 minute. Prep to move in Service Unit to swab well.