		Form C-103
NO. OF COPIES PECEIVED		Supersedes Old
DISTRIBUTION	NEW HENCO OF CONSERVATION COPRISSION	C-102 and C-103 Effective 1-1-65
ANTAFE	NEW MEXICO OIL CONSERVATION COMMISSION	2
11.6		5a, Indicute Type of Leaso
.5.G.S.		State Fee
AND OFFICE	MAR 2 9 1977	5. State Oil & Gas Leave No.
PERATOR		K-6698
	G. C. C. Walle	
THE TOTAL PROPERTY AND A SECOND PORTY AND A SECOND	DRY NOTICES AND REFERENCE TO A SUPPERSON RESERVOIR.	
USE TARKET	CATION FOR PERMIT LO (COPIL C-101) FOR CATA PACEDONIS.)	7. Unit Agreement Mane
01L	Yearen	
week L.J week L.J	OTHER-	6. Farm of Lease Name
Name of Operator	*:To come one	Amogo-State
seri T	, HATTER	9. Well No.
Address of Operator	and and Cimela Sen incels Perse 76901	1
	codland Circle, San Angelo, Texas 76901	10. Field and Pool, or Wildoot
Lecution of Well	550 south 1.725	wildcat - Queen
UNIT LETTER	550 FEET FROM THE SOUTH LINE AND 1,725 FEET	LEON MONTH
	24 48 9 20 E	
THE WEST LINE, SE	CTION 36 TOWNSHIP 15 S RANGE 29 E	rnow []]]]]]]]]]
arearen ararrir	15, Elevation (Show whether DF, RT, GR, etc.)	12, County
	3842 GL	Chaves
	ek Appropriate Box To Indicate Nature of Notice, Report o	r Other Data
NOTICE OF	FINTENTION TO: SUBSEQ	JENT REPORT OF:
		1
ERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
EMPCRARILY ABARDON	COMMENCE DRILLING OPHS.	PLUG AND ABAHDONMENT
	CHANGE PLANS CASING TEST AND CEMENT JOB	·
ULL OR ALTER CASING		·
CULL OR ALTER CASING	OTHER	
OTHER	other d Operations (Clearly state all pertinent details, and give pertinent dates, inc TD 1993	Inding estimated date of starting any proposed
Completed Ope 1) Ren tubing mix mud; 2) pumped 35 3) pumped 35 4) pumped 35 5) pumped 10	OTHER	luding estimated date of starting any proposed 1977: ing 9# brine to
Completed Ope 1) Ran tubing mix mud; 2) pumped 35; 4) pumped 35; 5) pumped 10; 6) erected dr	d Operations (Clearly state all pertinent details, and give pertinent dates, inc. 1993 rations to Plug and Abandon on March 10, to 1,980', circulated hole with mud, us sacks cement at 1,980'-TD 1,993'; sacks cement 1,100' to 1,200'; sacks cement 315' to 415', surface casing sacks cement in top of surface casing; y hole marker.	1977: ing 9# brine to g shoe at 365' (368 log); ad
Completed Ope 1) Ran tubing mix mud; 2) pumped 35; 4) pumped 35; 5) pumped 10; 6) erected dr	other doperations (Clearly state all pertinent details, and give pertinent dates, inc. 1993 rations to Plug and Abandon on March 10, to 1,980', circulated hole with mud, us. sacks cement at 1,980'-TD 1,993'; sacks cement 1,100' to 1,200'; sacks cement 315' to 415', surface casing, as acks cement in top of surface casing; and provided the sacks cement in top of surface casing; as y hole marker.	luding estimated date of starting any proposed 1977: ing 9# brine to
Completed Ope 1) Ran tubing mix mud; 2) pumped 35; 4) pumped 35; 5) pumped 10; 6) erected dr	d Operations (Clearly state all pertinent details, and give pertinent dates, inc. 1993 rations to Plug and Abandon on March 10, to 1,980', circulated hole with mud, us sacks cement at 1,980'-TD 1,993'; sacks cement 1,100' to 1,200'; sacks cement 315' to 415', surface casing sacks cement in top of surface casing; y hole marker.	1977: ing 9# brine to g shoe at 365' (368 log); ad

CONDITIONS OF APPROVAL, IF ANYI