

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

NMOCC COPY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-2365

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals.)

1. **RECEIVED**

OIL WELL ☐ GAS WELL ☐ OTHER ☒ **Dry Hole**

2. NAME OF OPERATOR

Read & Stevens, Inc.

OCT 11 1977

3. ADDRESS OF OPERATOR

P.O. Box 2126, Roswell, New Mexico 80201.

4. LOCATION OF WELL (Report location clearly and in accordance with **ARTESIA, NEW MEXICO**)
See also space 17 below.)

At surface
1650' FSL & 990' FWL Sec. 18, T-15-S, R-28-E, N.M.P.M.

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Rose

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Buffalo Valley Penn. Gas

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 18-T-15-S, R-28-E, N.M.P.M.

12. COUNTY OR PARISH

Chaves

13. STATE

N.M.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3610.2' GR-3622' RKB

16. **Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data**

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☒

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD 9135'. On 6-13-77, received verbal permission from R.L. Beckman, U.S.G.S., Artesia, N.M., to plug and abandon as follows:

1. Set 52 sx. cement plug 7350'-7200'.
2. Set 52 sx. cement plug 6350'-5200'.
3. Set 35 sx. cement plug 3300'-3200'.
4. Set 35 sx. cement plug 1850'-1750'.
5. Cut and pull 8 5/8" casing.
6. Set 60 sx. cement plug 50' in and 50' out of 8 5/8" casing stub.
7. Set 85 sx. cement plug 423'-323'.
8. Set 10 sx. cement plug 10'-surface.
9. Install regulation marker.

RECEIVED
SEP 30 1977
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

R. L. Beckman

TITLE **Agent**

DATE **9-28-77**

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APPROVED
OCT - 7 1977
R. L. Beckman
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963-O-685229

687-851