Bureau of Land Management Roswell, New Mexico
Lease No. 11M 3/370
Operator Depco Fric.
Well Name_ / Papalotes Federal
Sec. 14 T. 15 5. R. 281E.
Footage J90 FNZ & 1980 FUL

"STANDARD <u>ABANDONMENT</u> STIPULATIONS FOR ALL DRILLING IN RELATION TO OIL AND GAS ACTIVITIES IN THE <u>ROSWELL DISTRICT</u>"

(The following list of 5 stipulations are some of the more commonly used abandonment stipulations for oil and gas drilling operations in southeastern New Mexico. The blocks checkmarked in red designate the stipulations applicable to the particular abandonment notice listed above. Special or additional stipulations (if any) are written in under #6.)

Z:

BARKE BILLING ADDA - ADDA

- The surface location is to be cleaned and leveled as per U.S.G.S. requirements.
- 2. <u>Private Surface:</u> Abandonment stipulations to coincide with operator-landowner agreement. (Where no agreement exists, the BLM will be contacted to provide abandonment stipulations.)
  - 3. The drill pad and \_\_\_\_\_\_ miles of access road should be ripped to a minimum of 12" in depth.
- The drill site (including reserve pit area) and \_\_\_\_\_\_ miles of access road should be reseeded according to the attached recommendations.
- 5. All ripped surfaces are to be protected from vehicular travel by constructing a dead-end ditch and earthen barricade at the entrance to these ripped areas. The barricade is to be constructed using spoil material from the ditch and should be of sufficient magnitude to discourage vehicle entry.
- 6.

Speical Stipulations: