

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - C-103 FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	2. Name of Operator Liberty Oil and Gas Corporation ✓	3. Address of Operator P. O. Drawer 430, Livonia, Louisiana 70755	4. Location of Well UNIT LETTER <u>G</u> <u>1,650</u> FEET FROM THE <u>North</u> LINE AND <u>1,980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>21</u> TOWNSHIP <u>17S</u> RANGE <u>17E</u> N.M.P.M.	5. State Oil & Gas Lease No.	6. State Indicate Type of Lease State ☐ Fee ☒
15. Elevation (Show whether DF, RT, GR, etc.) <u>54,736</u> Ground				7. Unit Agreement Name	8. Farm or Lease Name T. L. watts
12. County Chaves				9. Well No. I	10. Field and Pool, or Wildcat Wildcat

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

total depth 5485-

March 8, 1981 - Plug and Abandon. Procedure used in T. L. Watts #1 Well.
First Plug - 5,239' to 5,340' with 40 sx class =C= cmt. Plug in place at 4:15 a.m. 3/8/81.
Second Plug - 4,270' to 4,370' with 40 sx class =C= cmt. Plug in place at 4:46 a.m. 3/8/81.
Third Plug - 2,875' to 2,975' with 40 sx class =C= cmt. Plug in place at 6:11 a.m. 3/8/81.
Fourth plug - 1,750' to 1,850' with 40 sx class =C= cmt. with 40% cacl. Plug in place at 7:48 a.m. 3/8/81.
March 8, 1981 - Wait on cmt. 4 hrs. Go in hole. Tag top of cmt. at 1,700'.
Fifth Plug - 1,090' to 1,190' with 60 sx class =C= cmt. Plug in place at 12:10 a.m. 3/8/81.
Lay down drill pipe - Remove B.O.P.s.
No top plug used.
Well released to Rancher (T. L. Watts) for use as water well.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED L. L. On TITLE Foreman DATE 3/9/81

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form O-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
RECORDS	
LAND OFFICE	
OPERATOR	

3a. Indicate Type of Lease
State ☐ Fee ☒
3. State Oil & Gas Lease No.

SUMMARY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPERATE PLUG BACK ON DIFFERENT RESERVOIR.
USE THE APPLICATION FOR RE-ENTRY TO A FORM O-101 FOR SUCH PROPOSALS)

1. Name of Operator
Liberty Oil and Gas Corporation ✓
2. Address of Operator
P. O. Drawer 430, Livonia, Louisiana 70755
3. Location of Well
UNIT LETTER G 1,650 FEET FROM THE North LINE AND 1,980 FEET FROM
THE East LINE, SECTION 21 TOWNSHIP 17S RANGE 17E NMPM.

7. Unit Agreement Name
8. Name of Lease Owner
T. L. watts
9. Well No.
I
10. Field and Pool, or Wellbore
Watts
12. County
Chaves

15. Elevation (Show whether DB, RT, GK, etc.)
54,736 Ground

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

total depth 5485'
March 8, 1981 - Plug and Abandon. Procedure used in T. L. Watts #1 Well.
First Plug - 5,239' to 5,340' with 40 sx class =C= cmt. Plug in place at 4:15 a.m. 3/8/81.
Second Plug - 4,270' to 4,370' with 40 sx class =C= cmt. Plug in place at 4:46 a.m. 3/8/81.
Third Plug - 2,875' to 2,975' with 40 sx class =C= cmt. Plug in place at 6:11 a.m. 3/8/81.
Fourth plug - 1,750' to 1,850' with 40 sx class =C= cmt. with 40% cacl. Plug in place at 7:48 a.m. 3/8/81.
March 8, 1981 - Wait on cmt. 4 hrs. Go in hole. Tag top of cmt. at 1,700'.
Fifth Plug - 1,090' to 1,190' with 60 sx class =C= cmt. Plug in place at 12:10 a.m. 3/8/81.
Lay down drill pipe - Remove B.O.P.s.
No top plug used.
Well released to Rancher (T. L. Watts) for use as water well.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED G. L. Qu TITLE Foreman DATE 3/9/81

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐
1. Name of Operator
Liberty Oil and Gas Corporation ✓
2. Address of Operator
P. O. Drawer 430, Livonia, Louisiana 70755
3. Location of Well
UNIT LETTER G 1,650 FEET FROM THE North LINE AND 1,980 FEET FROM
THE East LINE, SECTION 21 TOWNSHIP 17S RANGE 17E NMPM.

7. Unit Agreement Name
8. Farm or Lease Name
T. L. Watts
9. Well No.
I
10. Field and Pool, or Wholen
21st
12. County
Chaves

15. Elevation (Show whether DF, RT, GR, etc.)
54,736 Ground

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

total depth 5485

March 8, 1981 - Plug and Abandon. Procedure used in T. L. Watts #1 Well.
First Plug - 5,239' to 5,340' with 40 sx class =C= cmt. Plug in place at 4:15 a.m. 3/8/81.
Second Plug - 4,270' to 4,370' with 40 sx class =C= cmt. Plug in place at 4:46 a.m. 3/8/81.
Third Plug - 2,875' to 2,975' with 40 sx class =C= cmt. Plug in place at 6:11 a.m. 3/8/81.
Fourth plug - 1,750' to 1,850' with 40 sx class =C= cmt. with 40% cacl. Plug in place at 7:48 a.m. 3/8/81.
March 8, 1981 - Wait on cmt. 4 hrs. Go in hole. Tag top of cmt. at 1,700'.
Fifth Plug - 1,090' to 1,190' with 60 sx class =C= cmt. Plug in place at 12:10 a.m. 3/8/81.
Lay down drill pipe - Remove B.O.P.s.
No top plug used.
Well released to Rancher (T. L. Watts) for use as water well.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED L. L. Qu TITLE Foreman DATE 3/9/81

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT DEPTH. USE APPLICATION FOR PERMIT - (FORM C-101) FOR SUCH PROPOSALS.)

RECEIVED

OIL WELL ☒ GAS WELL ☐ OTHER ☐
1. Name of Operator
Liberty Oil and Gas Corporation
2. Address of Operator
P. O. Drawer 430, Livonia, Louisiana 70755
3. Location of Well
UNIT LETTER G 1,650 FEET FROM THE North LINE AND 1,980 FEET FROM
THE East LINE, SECTION 21 TOWNSHIP 17S RANGE 17E NMPM.

MAR 11 1981

O. C. O.
AREA OFFICE

7. Unit Agreement Name
8. Farm or Lease Name
T. L. Watts
9. Well No.
I
10. Field and Pool, or Wildcat
Wildcat
12. County
Chaves

15. Elevation (Show whether DF, RT, GR, etc.)
54,736 Ground

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

total Depth 5485'

March 8, 1981 - Plug and Abandon. Procedure used in T. L. Watts #1 Well.
First Plug - 5,239' to 5,340' with 40 sx class =C= cmt. Plug in place at 4:15 a.m. 3/8/81.
Second Plug - 4,270' to 4,370' with 40 sx class =C= cmt. Plug in place at 4:46 a.m. 3/8/81.
Third Plug - 2,875' to 2,975' with 40 sx class =C= cmt. Plug in place at 6:11 a.m. 3/8/81.
Fourth plug - 1,750' to 1,850' with 40 sx class =C= cmt. with 40% cacl. Plug in place at 7:48 a.m. 3/8/81.
March 8, 1981 - Wait on cmt. 4 hrs. Go in hole. Tag top of cmt. at 1,700'.
Fifth Plug - 1,090' to 1,190' with 60 sx class =C= cmt. Plug in place at 12:10 a.m. 3/8/81.
Lay down drill pipe - Remove B.O.P.s.
No top plug used.
Well released to Rancher (T. L. Watts) for use as water well.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED G. L. Qu TITLE Foreman DATE 3/9/81

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: